Sanitary Sewer Element



# **Table of Contents**

| 10.1 | Regula  | tory Framework                                      | 10-1  |
|------|---------|---|-------|
|      | 10.1.1  | Federal Regulations                                 | 10-1  |
|      | 10.1.2  | State Regulations                                   | 10-1  |
|      | 10.1.3  | Local Regulations                                   | 10-3  |
| 10.2 | Existin | g Facilities  | 10-3  |
|      | 10.2.1  | On-Site Disposal Systems                            | 10-4  |
|      | 10.2.2  | Alternative On-Site Disposal Systems                | 10-9  |
|      | 10.2.3  | Centralized Systems                                 | 10-12 |
| 10.3 | Assess  | ment and Inspection Programs                        | 10-33 |
|      | 10.3.1  | Septic Tank Inspection Program                      | 10-33 |
|      | 10.3.2  | Water Quality Monitoring                            | 10-34 |
|      | 10.3.3  | Resource Management                                 | 10-37 |
|      | 10.3.4  | Development of the Sanitary Wastewater/             |       |
|      |         | Stormwater Master Plan                              | 10-38 |
| 10.4 | Propos  | sed Level of Service (LOS) Standards                | 10-39 |
|      | 10.4.1  | Package Treatment Plants                            | 10-39 |
|      | 10.4.2  | On Site Disposal Systems (OSDS)                     | 10-39 |
|      | 10.4.3  | Present and Projected Future Ability to             |       |
|      |         | Meet Level of Service Standards                     | 10-39 |
|      | 10.4.4  |   |       |
|      |         | Inadequacies and Policy Constraints                 | 10-40 |
| 10.5 | Sanita  | ry Wastewater/Stormwater Management Master Plan     | 10-40 |
|      | 10.5.1  | Phase One: Design, Analysis and Approval of         |       |
|      |         | Water Quality Monitoring Network                    | 10-41 |
|      | 10.5.2  | Phase Two: Data Collection, Monitoring and Analysis | 10-44 |
|      | 10.5.3  | Phase Three: Development of the Sanitary            |       |
|      |         | Wastewater/Stormwater Management Master Plan        | 10-46 |
|      | Riblio  | graphy  | 10-48 |

# List of Tables

| Table 10.1  | Types of OSDS and Use By Percentage                     |
|-------------|---|
| Table 10.2  | Septic Tank Effluent Quality                            |
| Table 10.3  | Typical Effluent Concentration from Septic Tank Systems |
| Table 10.4  | Sanitary Sewer Package Treatment Plant Operation Report |
| Table 10.5  | Facilities Discharging to Surface Waste                 |
| Table 10.6  | Facilities Currently Under DER Enforcement Action       |
| List of Fig | gures   |
| Figure 10.1 | Typical Cross-Section of a Mound System10-10            |

# 10.0 Sanitary Sewer Element

The treatment of sewage and the disposal of wastewater within unincorporated Monroe County has traditionally been accomplished through either on-site treatment and disposal involving the use of septic tanks or small and intermediate sized, privately-owned wastewater treatment package plants. Factors such as rapid growth and the reliance upon private enterprise for the construction and operation of wastewater treatment facilities has caused a proliferation of small package treatment plants and an enormous inventory of individual septic tanks. Current wastewater treatment practices combined with severely limited soils and high land use densities result in increased potential for ground and surface water contamination. The inventory and analysis of data contained herein address existing and future conditions within the context of the Florida Keys' designation as an "Area of Critical State Concern," and the designation of adjacent waters as "Outstanding Florida Waters."

While a number of preliminary studies and reports have been generated in recent years regarding nutrient contamination of nearshore water quality in the Florida Keys, none have been conducted as a part of a coherently-designed scientific evaluation of all potential sources of contamination throughout Monroe County. The Board of County Commissioners has recognized this and has committed to the preparation and implementation of a Sanitary Wastewater and Stormwater Management Master Plan (SW/SMMP) and implementation resulting in improvement tonearshore water quality.

## 10.1 Regulatory Framework

## 10.1.1 Federal Regulations

The Federal Water Pollution Control Act (PL 92-500) is the controlling national legislation relating to the provision of sanitary sewer service. The goal of this act is the restoration and/or maintenance of the chemical, physical and biological integrity of the nation's waters. The Act established the national policy aimed at implementing area-wide waste treatment and management programs to ensure adequate control of pollutant sources. Under Section 201 of PL 92-500, grants were made available to local governments to construct facilities to treat "point sources" of pollution, which include effluent from sewage treatment processes. The U.S. Environment Protection Agency is responsible for implementing the Act. During the 1970's Federal grant monies were generally available to local governments showing a need for expanded sewage treatment capacity, but today such funds are scarce.

## 10.1.2 State Regulations

The Florida Department of Environmental Regulation (DER) is responsible for ensuring that the State carries out responsibilities assigned to it under PL 92-500. DER has adopted rules for the regulation of wastewater facilities in Chapter 17-6, F.A.C. These rules apply to facilities which treat flows exceeding 10,000 gallons per day for domestic establishments, 5,000 gallons per day for food service establishments, and where the sewage contains industrial, toxic or hazardous chemical waste.

Recognition of the nearshore waters of the Florida Keys as a resource of the highest order spurred protective legislation in 1974 designating the Florida Keys as an "Area of Critical State Concern," under Chapter 380 of the Florida Statutes. Ten years later, "The Principles for Guiding Development in the Florida Keys Area of Critical State Concern" were adopted to "insure a water management system that will reverse the deterioration of water quality and provide optimum utilization of our limited aquatic resources, facilitate orderly and well-planned development, and protect the health, welfare, safety, and quality of life of the residents of this state."

Class III surface waters of the Florida Keys, in addition were classified in 1985 as "Outstanding Florida Waters" (OFW's), and as such, may not be degraded as a result of any human activity or discharge. Class III water quality criteria provided in Florida's Administrative Code apply to the OFW's of the Florida Keys. Rule 17-3 states that DER considers excessive nutrients (total nitrogen and total phosphorous) to be "one of the most severe water quality problems facing the State." Section 17-3.041 gives special protection to the Florida Keys as OFW's. OFW is the highest protection, in areas which have exceptional recreational or ecological significance, and includes all the Florida Keys except the Key West outfall, Stock Island power plant mixing zone, and certain artificial water bodies (see Section 10.3.2). Compliance with OFW requirements relates only to sources permitted after the OFW designation.

The Florida Department of Health and Rehabilitation Services (HRS) regulates septic tank and drainfield installation within the State. These requirements have been adopted by rule in Chapter 10D-6, F.A.C., which specify capacity limits (5,000/10,000 GPD) and drainfield design criteria. Chapter 381.272(12), F.S., (On-site Sewage Disposal Systems; Installations; Conditions) also required the HRS to promulgate a special rule authorizing such systems in the unique geology of the Florida Keys and portions of Dade County "which take into consideration these unique soil conditions, and which consider water table elevations, densities, and setback requirements." Part II of Chapter 10D-6 F.A.C., became effective on July 15, 1986, pursuant to the aforementioned section. Chapter 10D-6, Part II is currently under revision by HRS to provide additional criteria for the protection of public health.

According to Section 10D-6.41 (8)(a) (b) and (c), any wastewater which contains industrial or toxic waste is prohibited from septic tanks. In addition, areas zoned for industrial or manufacturing, or its equivalent, are prohibited from using septic tanks unless the use is for domestic waste disposal. Food establishments generating more than 5,000 gallons a day are also prohibited from using septic tanks. In Monroe County the DER reviews building permits for commercial use to determine if the original use is a generator of hazardous or toxic waste. Examples of uses which would not be permitted to use a septic tank are dry cleaners, printers, and photo labs. Rule 10D-6.061(4), F.A.C. further specifies that:

"subdivisions and lots platted after December 31, 1971, and served by a public water system or cisterns may be developed utilizing on-site sewage disposal systems provided there are no more than four lots per acre. Subdivisions and lots platted after December 31, 1971, may be developed with private potable wells and on-site sewage disposal systems provided each lot has a minimum area of at least 1/2 acre. For lots platted prior to 1972, minimum lot size requirements shall not apply."

Chapter 381.272, F.S. requires that every on-site disposal system except approved grey water systems connect to a publicly or investor owned sewage system within 365 days after such a system is available. Monroe County should require that notification of this state requirement be placed on any building permit issued for development associated with the use of OSDS in order to emphasize to owners or developers that the use of OSDS may be a temporary sewage disposal method in the event that publicly or privately owned sewage systems become available. In addition, provisions must be made for the inclusion of sewer utility easements and right-of-way in a subdivision and the developer is required to notify the buyer of a lot of the provisions contained in Chapter 381.272 F.S.

## 10.1.3 Local Regulations

At the present time, the treatment and disposal of sewage in Monroe County is provided by the private sector. There are no public sewage treatment facilities operating in the unincorporated County. Accordingly, aside from current County Code requirements which mandate OSDS inspections every three years and prohibit OSDS in salt marsh and buttonwood areas, regulation is provided solely by the HRS and the DER.

Enabling legislation currently exists for the establishment of public sewer systems in Monroe County. As enacted by the Florida State Legislature, the Florida Keys Aqueduct Authority (FKAA) retains legal jurisdiction to purchase, construct, manage and operate sewage collection, treatment and disposal services to any entity or area of the County. The Authority has the power to create sewer districts covering any area of the County, subject to approval by the Board of County Commissioners for Monroe County. At present, the FKAA has yet to exercise this jurisdiction as no centralized sanitary sewer systems have been constructed.

## 10.2 Existing Facilities

Sanitary sewer facilities operating in unincorporated Monroe County consist of regulated and unregulated on-site disposal systems (OSDS) and package treatment plants. At the present time approximately 65 percent of the wastewater flow is treated by OSDS. The remaining 35 percent of the flow is treated by package treatment plants. Aside from the City of Key West's sewage system, no publicly operated wastewater treatment facilities are in operation in Monroe County. The existing inventory of sewage facilities in Monroe County includes approximately 24,000 septic tanks regulated by HRS, 193 small package treatment plants regulated by DER in unincorporated Monroe County, 99 marinas and 15,000 boats regulated by the U.S. Coast Guard, and 5000 unpermitted and unregulated cesspools. Commercial facilities (such as restaurants, motels, and campgrounds) and multiple-family dwellings (condominium and apartment buildings) are served by "package" plants, ranging in capacity from 0.002 to 0.6 million gallons/day (MGD). All of these package plants serve site specific projects and are privately owned, operated and maintained. One and two-family dwellings commonly use septic tanks, and at the present time, many campgrounds and mobile home parks in the County are also serviced by septic tanks.

As previously indicated, the Florida Keys Aqueduct Authority (FKAA) through its enabling legislation has the power to create sewer districts within the geographic boundaries of its service area upon approval of the majority of the County Commission. The Authority has power to impose the necessary fees and other charges required to construct and operate sewage collection, treatment and disposal

facilities. The FKAA has not formally initiated any studies or other implementation activities to date. During the implementation of the policies contained in the Comprehensive Plan, the County, in conjunction with the FKAA and other entities, will undertake the development of a Sanitary Wastewater/Stormwater Management Master Plan (SW/SMMP) for all of the unincorporated County. Policies adopted by the Monroe County Commission during the development of the Comprehensive Plan will serve as the guidelines for the development of the parameters under which the SW/SMMP will be undertaken. At the present time it is anticipated that the SW/SMMP will be completed by October 1999. To the greatest extent feasible, the SW/SMMP will be implemented through amendments to the Monroe County Land Development Regulations when definitive conclusions have been reached.

## 10.2.1 On-Site Disposal Systems

The State of Florida Department of Health and Rehabilitative Services (HRS) is the entity responsible for the issuance of permits for on-site disposal systems. Chapter 10D-6 F.A.C., Standards for On-site Sewage Disposal Systems, provides the regulatory framework under which the HRS regulates on-site disposal systems. Chapter 10D-6 F.A.C. sets forth the state wide density standards related to the utilization of on-site disposal systems as follows:

10-D6.061 F.A.C. (4) Subdivisions and lots platted after December 31, 1971 and served by a public water system or cisterns may be developed utilizing on-site sewage disposal systems provided there are no more than four (4) lots per acre. Subdivisions and lots platted after December 31, 1971 may be developed with private potable wells and on-site sewage disposal systems provided each lot has a minimum area of at least 1/2 acre. For lots platted prior to 1972 minimum lot size requirements shall not apply(emphasis added).

The provision of 10D-6 F.A.C., which allows for an exemption of the minimum lot size requirements for lots platted prior to 1972, has serious ramifications in the Keys in that of the 15,000 platted buildable lots approximately 90 to 95 percent are pre-1972. If the State requirements are the only regulations which must be adhered to relative to installation of on-site disposal systems (the Monroe County Land Development Regulations specifically reference Chapter 10D-6 as the County requirements) much of the platted land in the Keys might be considered to be exempt from the density standards pertaining to the application of OSDS.

The most common type of on-site sewage disposal system (OSDS) in Monroe County is the septic tank system. The basic septic tank system consists of two components:

- (1) A buried tank to collect waterborne domestic wastes and allow scum, grease, and settleable solids to be removed from the liquid by gravity separation; and
- (2) A subsurface soil absorption system to allow clarified effluent to percolate into the soil and eventually reach the ground water.

Within Monroe County as a whole, on-site disposal systems currently includes approximately 24,000 septic tanks and 5,000 cesspools. These septic tanks and cesspools are being mapped in conjunction with preparation of the Comprehensive Plan. This mapping effort will be utilized during the initial phases of the SW/SMMP. The most commonly used septic tank system in Monroe County is the single

tank system. Standards for on-site wastewater treatment facilities have been established for Monroe County by HRS and are implemented by the Monroe County Department of Health.

As part of Florida's OSDS research project, all county environmental health programs were surveyed in August 1986 by the HRS. Results of this survey for Monroe County show that 641 OSDS permits were issued in 1983, 713 were issued in 1984, 1979 were issued in 1985, and approximately 1500 were issued in 1986, with 95 percent of the systems located in platted subdivisions. The types of OSDS systems installed during this time are shown in Table 10.1.

Table 10.1

Types of OSDS and Use, By Percentage

| System  | 1984 | 1985 | 1986 |
|---|------|------|------|
| Conventional Septic Tank/ Drainfield Systems: |      |      |      |
| Trenches                                      | 0%   | 0%   | 0%   |
| Beds  | 60%  | 54%  | 44%  |
| Systems in Fill (excl. mounds)                | 35%  | 38%  | 40%  |
| Mound Systems                                 | 5%   | 7%   | 10%  |
| Graveless Systems                             | 0%   | 0%   | 0%   |
| Blackwater/Graywater Systems                  | 0%   | 0%   | 0%   |
| Home Aerobic Unit/Drainfield<br>Systems       | 0%   | 1%   | 4%   |
| Home Aerobic Unit/Borehole                    | 0%   | 0%   | 2%   |

Source: Florida Health and Rehabilitative Services, 1986

As reflected in this survey, conventional septic tanks remain the most common type of OSDS installed in Monroe County. Prior to 1984, the predominant type of OSDS installed in Monroe County was the conventional septic tank with absorption beds. While the use of absorption beds has decreased in recent years, conventional systems using fills or mounds has increased along with alternate home aerobic units which utilize drainfields or injection wells.

When site conditions are favorable and septic tank systems are properly designed, constructed, and maintained, they can be efficient and economical alternatives to centralized wastewater treatment systems. Under unfavorable site conditions, such as high septic tank density, high seasonal rainfall, shallow ground water, or highly permeable soils, OSDS can be a significant source of nutrient and

bacterial ground water contamination. Sherman et al. (1988) indicated that virtually 100 percent of the soils in Monroe County are severely limited for conventional OSDS practices.

According to the provision of 10D-6 F.A.C., maintenance of on-site disposal systems is the responsibility of the person owning or controlling the property on which the on-site disposal system is installed. The minimum recommended time period between maintenance checks is specified as being three years. The Monroe County Land Development Regulations require that inspection affidavits be filed with the Planning Department by licensed contractors or engineers. The requirement is at the present time not being monitored or enforced and as a result mandatory HRS inspections are being proposed.

An additional monitoring requirement adopted by HRS and set forth in the special sections of Chapter 10D-6, Part II, which pertain to only portions of Dade County and all of Monroe County, requires that aerobic on-site disposal facilities be inspected at least three times a year and that the county public health unit monitor a representative sample of these units. At the present time, of the 350 aerobic treatment units for single family homes and commercial establishments treating up to 5,000 GPD permitted by the HRS - Monroe County Public Health Unit, there are approximately 184 aerobic on-site systems operating in unincorporated Monroe County. These aerobic systems can discharge effluent into either a drainfield system similar to what would be used for a septic tank system or through a gravel filter and then into a borehole extending a minimum of 50 feet deep. Of the units installed and operating, 120 are utilizing borehole discharge and 64 utilize drainfields. HRS has recently issued the reporting and monitoring requirements related to these aerobic systems through incorporation of the requirements in Chapter 10D-6, Part II. However, local enforcement of these requirements has not begun. Based on limited sampling conducted by DER from 1987 through 1989, data has indicated that many of these aerobic systems are not functioning in compliance with the National Sanitation Foundation standards which are referenced in Chapter 10D-6 and are utilized as defining the acceptable levels of treatment for aerobic sewage treatment units. Implementation of the adopted HRS monitoring requirements should begin to provide an indication of the appropriateness of future utilization of aerobic on-site disposal systems in the Keys.

Soil identification is probably the most useful information in determining site suitability for onsite wastewater facilities. The U.S. Department of Agriculture Soil Conservation Service (SCS) has prepared Detailed Soil Surveys for many of Florida's counties. These surveys can be useful in planning as they include information on depth to seasonal water table, flood potential, depth of suitable soil material, percolation rates, and limitations for various uses including on-site waste treatment systems. Tables 3.2 and 3.3 in Chapter 3.0 (Conservation and Coastal Management Element) indicate the characteristics of soils found in Monroe County. The limitations found for septic tank use, as recently determined by the SCS are shown in Table 3.4. As shown in these tables, all soils in Monroe County are rated "Severe" for the use of septic tank absorption fields. In October 1987, an HRS-funded research project by Kirkner and Ayres and Associates found that 70.5 percent of Monroe County soils have "very severe" and 29 percent have "severe" limitations for OSDS use.

As reported by DER in the 1988 Wastewater Treatment and Design Manual:

"When able to percolate downward through suitable soils, most pollutants are removed from effluents within relatively short distances. If there is insufficient depth of suitable soil between the drainfield and the groundwater table or an impervious layer, the partially treated effluent

will enter the groundwater system or flow laterally and break out into surface waters or drainage ditches. Pollutants have been found to travel great distances from their source when aided by the flow of groundwater."

The characteristics of septic tank effluent presented in Tables 10.2 and 10.3 indicate the potential for contamination of ground water from septic tank effluent. These contaminants include natural and synthetic organic compounds expressed in terms of BOD<sub>5</sub>, COD, TSS, nitrogen, phosphorous, and pathogens.

The performance requirement for Class I individual aerobic waste water treatment units is defined in Section 6 of the National Sanitation Foundation Standard Number 40: "Plants listed for Class I effluent must be shown to meet EPA Secondary Treatment Requirements for BOD<sub>5</sub>, SS and pH." These requirements are a 30-day average of 30 mg/1 for BOD<sub>5</sub> and SS, and a pH of 6.0 to 10.0. There are no requirements for nutrient reduction (National Sanitation Foundation, 1983).

Table 10.2 Septic Tank Effluent Quality

| Constituent             | Concentration (mg/1) |
|-------------------------|----------------------|
| BOD                     | 90-348               |
| COD                     | 150-720              |
| тос                     | <u>+</u> 129         |
| TS                      | <u>+</u> 820         |
| SS (89% 0.5-5.0 micron) | 40-350               |
| VSS                     | 80% SS               |
| TN                      | +25-36               |
| Organic N               | 30% TN               |
| Ammonia (NH4-N)         | 70% TN               |
| PO                      | 35-100               |
| Grease                  | 50-150               |
| E. coli                 | 106-108/100 ml       |

Source: Laak, 1980.

Table 10.3

Typical Effluent Concentrations from Septic Tank Systems

| Parameters<br>(mg/1) | Septic Tank<br>Effluent | Drain System<br>Effluent | % Removal in<br>Drain System |
|----------------------|-------------------------|--------------------------|------------------------------|
| Suspended solids     | 75                      | 18-53                    | 29-76                        |
| BOD5                 | 140                     | 28-84                    | 40-80                        |
| COD                  | 300                     | 57-142                   | 53-81                        |
| Total Nitrogen       | 40                      | 10-78*                   |                              |
| Total Phosphorous    | 15                      | · 6-9                    | 40-60                        |

Note: \*Reported as ammonia nitrogen.

Source: Canter and Knox. 1985.

Meetings with representatives from HRS and DER concluded that although numerous studies have been conducted relating to OSDS performance, there has been no definitive quantative conclusions concerning the relationships between septic tank effluent and nearshore water quality degradation. There is, however, reasonable suspicion that nutrient loading from regulated and unregulated OSDS contributes to nearshore water quality degradation. The Stipulated Agreement between Monroe County and the State of Florida Department of Community Affairs requires that standards for OSDS be based on environmental carrying capacity which address nutrient loading and maintains the quality of nearshore waters. These OSDS standards, as well as standards for all wastewater treatment and disposal techniques will be established as a result of the SW/SMMP.

As a starting point in conjunction with preparation of the Monroe County Comprehensive Plan, an inventory of all permitted and unpermitted septic tanks and cesspools has been undertaken. The methodology utilized is to map on one inch equals 200 feet aerial photos (flown 1991) the location of permitted septic tanks and aerobic units. The remaining residential structures, which appear to be inhabited or have the potential to be inhabited, and are not utilizing package treatment or central sewer facilities will be located on the aerial photos and identified as potentially utilizing unregulated on-site disposal systems. In addition, licensed septic tank installers and maintenance personnel will be interviewed in order to ascertain the location of unpermitted septic tanks or cesspools. It is expected that this effort, scheduled for completion concurrent with the adoption of the Comprehensive Plan, when compared with the results of the nearshore water quality monitoring program, will provide the necessary information to more nearly quantify the affects of septic tank/cesspool effluents onnearshore water quality.

#### 10.2.2 Alternative On-Site Disposal Systems

Florida, and specifically Monroe County, has a particularly high percentage of soils unsuited to conventional OSDS septic tank/absorption bed systems. If OSDS are to function properly in such soils, alternative systems which are designed to overcome the specific limitations, improve effluent treatment, and reduce the potential for groundwater contamination must be used. Various alternative types of treatment/disposal beyond the septic tank and drainfield or absorption bed are available for consideration.

#### A. Aerobic Treatment Units

Aerobic treatment units which utilize soil absorption systems or injection wells are sometimes used in place of conventional septic tanks. Fixed media filters can be used in combination with either septic tanks or aerobic units for providing additional treatment of effluent. The performance requirement for Class I individual aerobic waste water treatment units is defined in Section 6 of the National Sanitation Foundation Standard Number 40 which states that "plants listed for Class I effluent must be shown to meet EPA Secondary Treatment Requirements for BOD5, SS and pH." These requirements are a 30-day average of 30 mg/1 for BOD5, and SS, and a pH of 6.0 to 9.0. There are no requirements for nutrient reduction (National Sanitation Foundation, 1983).

Special rules which HRS adopted for portions of Dade County and for the Florida Keys (10D-6, Part II), contemplated the need for further monitoring and analysis of the impacts of certain alternate on-site sewage disposal systems. Rule 10D-6.063(2)(d)10, F.A.C., provides that:

The county public health unit shall, at least annually, monitor the maintenance and performance of aerobic treatment units for a determination of the effectiveness of the provisions of paragraph 10D-6.063(2)(d), (Part II) in assuring proper operation, maintenance, performance and utilization of aerobic treatment unit systems.

Similar requirements are found in Rule 10D-6.063(3)(e), F.A.C. Though the complete monitoring and reporting requirements have not been implemented to date by HRS, some limited monitoring data has been generated. Samples were taken in May 1987, August, 1988 and February 1989, and were analyzed by the DER in Marathon. This recent aerobic treatment unit data has suggested that in the Florida Keys, many of these systems are not functioning in compliance with the current National Science Foundation (NSF) standards. The most recent data was obtained from Jet and Multiflow aerobic treatment units installed on Little Torch Key. Some of the units sampled that did not meet these standards were Rotordisk units which have not yet been approved by NSF. Although it is difficult to correlate the limited samples available with the testing methodologies contained in the NSF standard, half of the aerobic units tested in August 1988 exceeded the values for BOD5, while half of the May 1987 samples did not meet the 85 percent removal criterion for TSS.


Though alternative OSDS systems have been shown generally to provide improved treatment of sewage relative to conventional septic tanks, further monitoring and evaluation of these systems by HRS is essential to ensure the protection of public health and water quality in the Florida Keys. Additionally, concerns over recent sampling results should not preclude the consideration of other types of alternate and experimental systems. Nitrogen and phosphorous concentrations in wastewater may be reduced through specifically designed systems. Such systems may be utilized for OSDS and package

treatment plants. They must be carefully designed, constructed, operated and maintained to achieve the desired results. They are inherently more sophisticated and require a substantially higher level of care then normally afforded OSDS and small treatment plants. Alternate and experimental OSDS which consider BMP's and best available technologies will be investigated in the initial phase of the SW/SMMP.

#### B. Mounds

In Florida, the most common alternative to the conventional soil absorption system is the mound system. A properly constructed mound system utilizing good fill material may be more efficient than an equally well constructed conventional system in marginal or unsatisfactory natural subsurface soils. The objective of mound systems is to effectively treat sewage before it reaches ground or surface waters. This is done essentially by raising the absorption field above natural soils and increasing the distance between the water table and the drainfield by using suitable fill material. Mounds can be utilized to provide effluent treatment and disposal from a septic tank, aerobic unit, or other treatment unit. Minimum requirements for construction, and criteria for the location of mounds, are contained in Chapter 10D-6, F.A.C. Figure 10.1 is a schematic of a mound system.

Figure 10.1
Typical Cross-Section Of A Mound System



Source: Design Manual: Onsite Wastewater Treatment and Disposal Systems. EPA, October 1980.

Mound systems have certain advantages related directly to construction practices including:

- (a) percolating effluent leaving a mound enters the more permeable natural upper soil over a large area and can spread laterally until it is absorbed by the less permeable subsoil;
- (b) the clogging zone that eventually develops at the bottom of a drainfield may not clog the sand mound fill to the degree or rapidity it would in naturally very fine textured soils; and
- (c) smearing and compacting, which can occur when excavating wet fine textured subsoils, can be avoided.

It should be pointed out that Florida health officials require excavation and replacement of natural soils when they are not considered suitable for receiving effluent from mound systems. This is partly due to the fact that most Florida systems are not technically mound systems but, in most cases, are elevated drainfields.

## C. On-Site Management Systems

Various alternatives for on-site treatment and disposal of wastewater are available for use in Monroe County and will be identified in the SW/SMMP. It is important, however, when choosing an alternative that each component combined to make a total system should meet the following basic criteria (DER Wastewater Management Manual, 1988):

- (a) Produce an effluent of adequate quality for safe disposal;
- (b) Be simple (few mechanical parts; easy to maintain);
- (c) Be reliable (maintain consistent treatment);
- (d) Protect the aesthetic qualities of an area; and
- (e) Be acceptable to the homeowner or to the owner of another type of establishment (easy to use; creates no nuisance).

The term Best Management Practice (BMP) means a practice or combination of practices that are determined to be the most effective, practical means of preventing or reducing the amount of pollution generated by nonpoint sources to a level compatible with water quality goals. The selection of an appropriate BMP will depend greatly upon site conditions such as land use, topography, slope, water table elevation, and geology. BMP selection must be very site specific so as to assure proper BMP operation and prevent undesirable results such as protection of surface waters but contamination of ground water.

A successful on-site system produces an effluent which is compatible with the environment to which it is discharged. However, improper siting, installation or maintenance can lead to degradation of surface or ground waters. Two documents prepared by the DER - Septic Tank Nonpoint Source Element (June 1979) and Chapter 7 of the Florida Development Manual - contain extensive discussions on the proper use, design, construction, and maintenance of on-site wastewater systems. The first document was

prepared in cooperation with the Technical Advisory Committee on Septic Tanks whose membership included representatives from the HRS, county health departments, the septic tank industry, the Soil Conservation Service, and the Florida Home Builders Association. These documents are considered as the BMP manuals for on-site wastewater management.

Some of the BMP's suggested to minimize nonpoint source impacts from on-site wastewater systems include:

- (a) Since treatment is provided primarily by the soil matrix, sound site planning is essential. Careful evaluation of a site's soils, geology, topography, water table levels, hydrology, location of trees and vegetation and setback requirements must be undertaken to assure proper levels of treatment.
- (b) User education programs are vital since on-site systems are "out of sight, out of mind." It is important that users understand how the system works and how everyday activities can cause problems and reduce treatment efficiency.
- (c) Maintenance programs are essential since a septic tank can become too filled with solids, causing poor settling and the transfer of solids into the absorption system causing cloggings and system failure.
- (d) Alternative treatment and disposal systems such as aerobic units, granular media filters, and mound systems are especially applicable on sites with improper soil, water table, or geologic conditions. These alternative systems can provide a higher level of treatment than conventional systems.

#### 10.2.3 Centralized Systems

The most common type of centralized sanitary sewer system is the localized small sewage treatment facility, or "package plant" as they are commonly known. Large scale municipal sanitary sewer systems which generally provide services to densely populated areas are another type of centralized facility. These centralized facilities are comprised of three components which perform the basic functions of collection, treatment and disposal of sewage.

## A. Collection

The collection system is composed of a network of sewer pipes which collect sewage (also called wastewater) from individual establishments and convey it to a central location for treatment. The collection network is generally laid out in a pattern roughly analogous to the branching pattern of a tree. This classification scheme identifies sewers according to their location within the network. Since sewage flow within the network is from the periphery toward the treatment plant, this scheme allows for easy identification of components.

Interceptors are defined as sewers which connect directly to and convey sewage to the treatment plant. Trunk mains are defined as sewers which connect directly to and convey to an interceptor.

Wastewater collection systems utilize the force of gravity to the extent possible to convey sewage. Gravity systems work best in hilly terrain. In level terrain, a pumping system conveys sewage under pressure. The term "force main" is often applied to pressurized sewers without regard to their location within the network.

#### B. Treatment

The treatment plant component of the central sanitary sewer facility functions to remove solid and organic materials from the sewage. Depending on the proportion of materials removed, processes which accomplish treatment are generally grouped into one of the following four categories.

## **Primary Treatment**

Primary treatment removes between 30 and 35 percent of the organic materials and up to 50 percent of the solids from the sewage, and is the least expensive treatment. This level of treatment is also commonly referred to as physical treatment because screens and settling tanks are the most common methods used to remove the solids.

## **Secondary Treatment**

Secondary treatment removes between approximately 90 percent of total organic materials and suspended solids from sewage, and is the most common level of treatment provided by centralized facilities. This level of treatment generally requires multiple steps involving one biological process and one or more processes for removal of suspended solids, and is more expensive than primary treatment.

## **Tertiary Treatment**

Sewage may also contain large quantities of synthetic organic compounds or inorganic chemicals which may create pollution problems if not removed. Tertiary treatment is any treatment process beyond secondary treatment. The most common tertiary processes remove compounds of phosphorous and nitrogen. One method of tertiary treatment is spray irrigation, such as the irrigation of the golf course at Key Colony Beach. Because of the extra processes required tertiary treatment is more expensive than secondary treatment.

#### **Advanced Wastewater Treatment**

This term refers to tertiary treatment within the wastewater treatment plant itself to levels of water purity generally acceptable for discharge directly into surface waters. Advanced Wastewater Treatment (AWT) standards are set by law (s. 403.086 F.S.) in Florida. While AWT standards are very stringent, achieving this level of treatment gives a utility certain legal rights to discharge directly into surface waters. Currently, less than .05 percent of the wastewater treatment facilities in the State of Florida meet the AWT treatment standards. Advanced waste treatment is the most expensive method of treatment due to the additional plant and operations costs.

#### C. Disposal

Effluent is the treated wastewater which flows out of the treatment plant and disposal alternatives include discharge to a water body, discharge to the surficial aquifer through percolation ponds, bore holes, irrigation reuse or injection into deep aquifers. Proper effluent disposal is essential to protect surface and ground waters from environmental degradation. Class V injection wells are the prevailing sewage disposal method in the County for centralized systems such as package plants. As reported by

the DER in January, 1988, the secondarily treated effluent being disposed of via these injection wells in the Florida Keys is of relatively good quality for disposal into Class G-III groundwater. Though additional monitoring of injection wells by DER is scheduled, no violations of the "minimum criteria" for groundwater were found in 20 effluent samples collected by the DER in 1988. Further, localized data collected by the DER Marathon district office have shown that effluent disposed of in cased wells will have less effect on surface waters then effluent disposed of in drainfields.

On November 12, 1975, Monroe County adopted the following resolutions concerning wastewater treatment in the unincorporated County:

"Monroe County or the developer will provide for adequate wastewater treatment in existing and new development.

"Centralized public treatment facilities will be developed in urbanized areas as economic feasibility is evidenced. The Plan (Land Use Plan Update) will require phasing out of septic tanks and package treatment plants, with hook-ups to these new treatment plants as they become available.

"In new residential subdivisions where planned densities are sufficient to eventually support a central treatment facility, the use of septic tanks will be permitted only on an interim basis until sufficient development has occurred to permit the installation of the central treatment system by the development. New developments will be required to strictly conform to County and State design and operating standards for septic tanks and package treatment plants. Development in which private central treatment facilities will be required will be responsible for providing collection, treatment, and disposal methods that meet design and performance standards established by the County. New development in areas where public central treatment is available will be required to provide collection lines at the developer's expense."

In recognition of this possible solution and in anticipation of future population growth in unincorporated areas of the Florida Keys, the Monroe County 201 Facilities Plan (CH2M Hill, 1979) was developed for the DER to design centralized wastewater collection, treatment, and disposal facilities throughout the County. The Plan, however, was only to be implemented following completion of a water quality monitoring program that confirmed the need for site-specific centralized facilities by documenting consistent violation of State water quality standards in specific areas of the Florida Keys.

In addition, interim and long-range planning regarding selection of treatment process (whether OSDS or treatment plants), location or system type (OSDS, cluster systems, or central systems) should be based on the larger picture and overall benefits to the community and not on a site by site individual basis, as is currently the case. Handling wastewater from commercial and industrial establishments presents special problems which should be incorporated into the overall community planning process. Further, technology changes and population growth patterns indicate a need for flexibility in planning and the ability to retrofit existing and future OSDS when desirable.

The use of alternative sewer systems such as low-pressure grinder pumps (GP) and septic tank effluent pumps (STEP), small diameter gravity sewers, and vacuum sewer systems offer the flexibility and lower cost advantages which will be evaluated during development of the SW/SMMP.

There are 277 permitted package treatment plants operating in Monroe County of which 193 are in the unincorporated County. The location of the package treatment plants in the unincorporated county are shown on the Sanitary Sewer Map series of the Map Atlas. The treatment process utilized by the plants is a biological process which depends on providing a satisfactory habitat for biological organisms. These biological organisms are most commonly bacteria but may also include fungi, ciliates, rotifers and nematode worms. The most common process utilized is the activated sludge treatment process which provides the resident biological organisms with an environment in which they can digest the organic materials contained in the effluent. There are numerous modifications of the activated sludge process such as conventional, step aeration, and contact stabilization. The primary process utilized by the package treatment plants is the extended aeration process which provides an aeration detention time of at least 24 hours.

Package treatment plants are regulated by the provisions of Chapter 17-600 F.A.C., Domestic Wastewater Facilities, by the State of Florida Department of Environmental Regulations which provide minimum design waste treatment and disinfection standards. Wastewater treatment plants permitted for construction after January 1, 1982 and plants existing prior to January 1, 1982, which have had modifications which require compliance with the reclaimed water or effluent limitations required by 17-600 F.A.C. must be operated and maintained so as to attain at a minimum, the reclaimed water or effluent quality required by Rules 17-600.440 and 17-600.740(1) F.A.C. Treatment Plants existing prior to January 1, 1982, must at a minimum, meet reclaimed water of effluent limitations as specified in the facilities permit. All package treatment plants are required to provide secondary treatment of wastewater. All new domestic facilities and modifications to existing facilities are required at a minimum to be designed to achieve an effluent, after disinfection, containing not more than 20 mg/l BOD and 20 mg/l TSS, or 90 percent removal of each of the pollutants from the wastewater effluent, whichever is more stringent. An inventory of permitted package treatment plants operating in unincorporated Monroe County and the plants' design capacity, performance, and the level of biochemical oxygen demand and the total suspended solids in the effluent is presented in Table 10.4.

Due to the Outstanding Florida Waters designation in Monroe County, it is very difficult to obtain a new permit from the Department of Environmental Regulation and Environmental Protection Agency to construct an outfall to surface waters as a method of effluent disposal. There are currently six (6) wastewater treatment facilities discharging effluent via outfall to surface waters in unincorporated Monroe County (see Table 10.5).

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

| SERVICE                                 |
|---|
| POP                                     |
| Stock Island                            |
|   |
| Stock Island                            |
| -                                       |
| Stock Island                            |
|   |
| Stock Island                            |
|   |
| 8                                       |
|   |
| Boca Chica 2577                         |
| $\dashv$                                |
| Big Coppiu                              |
|   |
|   |
|   |
| Sugar Loaf 138                          |
|   |
| Sugar Loaf                              |
|   |
| Sugar Loaf 360                          |
|   |
| Sugar Loaf                              |
|   |
| 25.0 IR2779 Overceas Highway Snoar Leaf |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|  |          |      | A THE THE THE TWO MALES GROWN AND THE PROPERTY OF A PROPER |                     |         |        | AVERAGE |          |         |          |  |  |
|--|----------|------|--|---------------------|---------|--------|---------|----------|---------|----------|--|--|
|  |          |      |  |                     |         |        | PEAK    |          | AVERAGE |          |  |  |
|  | MAP      |      |  |                     |         | DESIGN | DAILY   | % OF     | ONTHL   | % OF     | RESPONSIBLE ENTITY   | BOD / TSS  |
|  | REF      |      |  |                     | SERVICE | CAP.   | FLOW    | DESIGN   | FLOW    | DESIGN   | PHONE  |  |
| SITE NAME  | *        | M.M. | SITE LOCATION  | KEY                 | POP.    | (LCD)  | (MGD)   | CAPACITY | (MGD)   | CAPACITY | The state of the s |  |
|  |          |      |  |                     |         |        |         |          |         |          | (305)451-2331  |  |
| Venture Out @ Cudjoe Key   | 15       | 25.0 | Route 2 Box 38   | Summerland          | 2000    | 70.0   | 0.04700 | 67.14%   | 0.03271 | 46.73%   | Don Peterson   | 4.0 / 8.0  |
|  |          |      |  |                     |         |        |         |          |         |          |  | The state of the s |
| Love Key Reef Resort   | 91       | 27.0 | M.M. 27 Overseas Highwa Ramrod   | Ramrod              |         | 10.0   | 0.00640 | 64.00%   | 0.00600 | 60.00%   | Joseph Glenn   | 5.0 / 2.4  |
|  |          |      |  |                     |         |        |         |          |         |          | (305)872-2215  | -  |
| Breezy Pine Trailer Park   | 1        | 29.8 | US 1@ Mile Marker 29.8   | Big Pinc            | 148     | 7.5    | 0.00350 | 46.67%   | 0.00312 | 41.60%   | W. Oblander  | 8.6 / 8.2  |
|  |          |      |  |                     |         |        |         |          |         |          |  |  |
| Big Pinc Plaza Shopping Cu.  | <u>e</u> | 30.5 | S.R. 940 & Wilder Road   | Big Pine            |         | 20.0   | 0.00920 | 46.00%   | 0.00614 | 30.70%   | 30.70% New Guarantee Fed. Sav.   | 9.4 / 3.4  |
|  |          |      |  |                     |         |        |         |          |         |          |  |  |
| Big Pine Motel   | ê.       | 30.7 | Overseas Highway   | Big Pine            | S       | 5.0    | 0.00472 | 94.40%   | 0.00386 | 77.20%   | Jesse Perkins  | 6.1 / 5.9  |
|  |          |      |  |                     |         |        |         |          |         |          | (512)494-3917  |  |
| Rig Pine Key Road Prison   | 8        | 32.0 | P.O. Box 509   | Big Pine            | 70      | 10.0   | 0.00090 | 99.00%   | 0.00707 | 70.71%   | L.L. Mainwright  | 7.0 / 8.5  |
|  |          |      |  |                     |         |        |         |          |         | •        |  |  |
| Bahia Honda #3   | 21       | 36.5 | US 1@ Mile Mark  | er 36.5 Bahia Honda |         | 5.0    | 0.00550 | 110.00%  | 0.00400 | 80.00%   | John Sommers   | 9.3 / 4.5  |
|  |          |      |  |                     |         |        |         |          |         |          | (904)487-1657  |  |
| Bubia Hemda #4   | 77       | 36.5 | US 1 @ Mile Marker 37  | Bahia Honda         |         | 8.3    | 0.00175 | 21.08%   | 0.00100 | 12.05%   | Michael Farmer   | 7.8 / 13.2   |
| - Company of the Comp |          |      |  |                     |         |        |         |          |         |          | (904)487-0999  |  |
| Babia Honda #2   | 23       | 37.0 | US I @ Mile Marker 37  | Bahia Honda         |         | 3.3    | 0.00250 | 75.76%   | 0.00200 | £19.09   | Florida D.N.R.   | 9.5 / 8.3  |
|  |          |      |  |                     |         |        |         |          |         |          | (904)487-0999  |  |
| Sunshine Key Travel Park   | 24       | 39.0 | Route 1 Box 790  | Ohio                | Se Se   | 99     | 0.06929 | 115.4894 | 0.04236 | 70.60%   | Capital Insurance Mgmt.  | 8.4 / 7.8  |
|  |          |      |  |                     |         |        |         |          |         |          |  |  |
| Hank's Nest Condo  | 25       | 47.0 | I Kyle Way   | Marathon            | 2       | 7.5    | 0.00443 | 29.07%   | 0.00443 | 59.07%   | John Hickin  | 3.1 / 14.6   |
|  |          |      |  |                     |         |        |         |          |         |          |  |  |
| Quay Restaurant  | 56       | 47.5 | 12650 Overseas Highway   | Marathon            |         | 15.0   | 0.00566 | 37.73%   | 0.00407 | 27.13%   | Steve Skropolis  | 11.7 / 16.9  |
| The second secon |          |      |  |                     |         |        |         |          |         |          |  |  |

TABLE 10 · 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|                                | -   |      |                                  |           |         |        | AVERAGE |          |               |          |                    |  |
|--------------------------------|-----|------|----------------------------------|-----------|---------|--------|---------|----------|---------------|----------|--------------------|--|
|                                |     |      |                                  |           |         |        | PEAK    |          | AVERAGE       | •        |                    |  |
| 2                              | MAP |      |                                  |           |         | DESIGN | DAILY   | % OF     | ONTH          | % OF     | RESPONSIBLE ENTITY | BOD / TSS  |
| æ                              | REF |      |                                  |           | SERVICE | CAP.   | FLOW    | DESIGN   | FLOW          | DESIGN   | PHONE              |  |
| SITE NAME                      | *   | M.M. | SITE LOCATION                    | KEY       | P0P.    | (dDT)  | (MGD)   | CAPACITY | (MGD)         | CAPACITY |                    |  |
| Galway Bay Mobile Home Park    | 27  | 47.5 | ,                                | Marathon  | 150     | 20.0   | 0.04758 | 237.90%  | 0.03115       | 155.75%  | Helen McDonough    | 8.9 / 30.9   |
|                                |     |      |                                  |           |         |        |         |          |               |          |                    |  |
|                                | 28  | 47.7 | 1996 Overseas Highway            | Marathon  | 225     | 40.0   | 0.01031 | 25.77%   | 0.00614       | 15.35%   | Jeroid Miles       | 4.3 / 13.3   |
|                                |     |      |                                  |           |         |        |         |          |               |          | (714)476-8180      |  |
| Pelican Restaurant             | 50  | 47.5 | 1490 Overseas Highway            | Marathon  | 150     | 7.5    | 0.00405 | 54.00%   | 0.00164       | 21.87%   | Rip Tosun          |  |
|                                |     |      |                                  |           |         |        |         |          |               |          | (305)664-5300      |  |
| Fard Blanco Resort             | 8   | 48.0 | 1996 Overscas Highway            | Marathon  |         | 10.0   | 0.00659 | 65.90%   | 0.00393       | 39.30%   | Jim Kelscy         | 4.7 / 3.1  |
|                                |     |      |                                  |           |         |        |         |          |               |          | (305)743-9012      |  |
| S. Switlik Elementary Sch.     | =   | 49.0 | 3400 Overseas Highway            | Manathon  | 642     | 15.0   | 0.00637 | 42.47%   | 0.00286       | 19.07%   | A J. Henriquez     | 3.1 / 6.8  |
|                                | 1   |      |                                  |           |         |        |         |          |               |          |                    |  |
| Hurricane Motor Lodge          | 32  | 48.6 | 4650 Overseas Highway            | Marathon  | 22      | 0.8    | 0.01133 | 141.63%  | 0.00808       | %00101   | Y. Littrell        | 8.4 / 6.1  |
|                                |     |      |                                  |           |         |        |         |          |               |          |                    |  |
| Casa Cayo Condo                | 33  | 49.0 | 49.0 1500 Overseas Highway N     | Marathon  |         | 3.2    | 0.00281 | 87.81%   | 0.00143       | 44.69%   | C.H.S. Corporation | 0.3 / 0.6  |
|                                | 1   |      |                                  |           |         |        |         |          |               |          | (305)743-6565      |  |
| Coral Lagoon Resort            | 7   | 48.8 | 12399 Overseas Highway A         | Marathon  | 25      | 8C.    | 0.00391 | 44.43%   | 0.00321       | 36.48%   | Richard Gross      | 1.2 / 0.9  |
|                                |     |      |                                  |           |         |        |         |          |               |          | (305)289-0121      | profession to the district which which the state of the first of the f |
| Fisherman's Hospital           | 35  | 49.1 | 3301 Overseas Highway N          | Marathon  | 150     | 21.0   | 0.00618 | 29.43%   | 0.00457       | 21.76%   | Joseph Suiter      | 3.0 / 7.8  |
|                                |     |      |                                  |           |         |        |         |          |               |          | (305)743-5533      |  |
| ady Alexander Condo            | ڃ   | 49.0 | 1505 Sombrero Beach Rea Marathon | Marathon  | S       | 5.0    | 0.00100 | 20.00%   | 0.00100       | 20.00%   | Mildred Stengel    | 0.4 / 4.7  |
|                                |     |      |                                  |           |         |        |         |          |               |          |                    | Tradition of the state of the s |
| Marathon High School           | 33  | 49.7 | 49.7 Sombrero Beach Road N       | Marathon  |         | 15.0   | 0.00730 | 48.67%   | 0.00286       | 19.07%   | Armando Henriquez  | 5.0 / 5.6  |
|                                |     |      |                                  |           |         |        |         |          |               |          | (305)296-6523      |  |
| Mid-Town Trailer Park          | 38  | 48.9 | 37th Street                      | Marathon  | 46      | 7.5    | 0.00586 | 78.13%   | 0.00286       | 38.13%   | Joseph Hendrickson | 8.7 / 13.3   |
|                                |     |      |                                  |           |         |        |         |          |               |          | (305)743-9379      |  |
| Mentor County Housing Authorit | 9   | 49.1 | 49.1 240 Sombrero Boulevard N    | Marzithon | 919     | 0.09   | Z.      | 900.0    | 0.00% 0.00833 | 13.88%   | Harry Haskins      | 7.9 / 4.0  |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|  |     | -     |                                  |          |         |          | AVERAGE |          |         |          |  |  |
|--|-----|-------|----------------------------------|----------|---------|----------|---------|----------|---------|----------|--|--|
|  |     |       |                                  |          |         |          | PEAK    |          | AVERAGE |          |  | ****   |
|  | MAP |       |                                  |          |         | DESIGN   | DAILY   | % OF     | ONTH.   | % OF     | RESPONSIBLE ENTITY                       | BOD / TSS  |
|  | REF |       |                                  |          | SERVICE | CAP.     | FLOW    | DESIGN   | FLOW    | DESIGN   | PHONE                                    |  |
| SITE NAME  | *   | M.M   | SITE LOCATION                    | KEY      | POP.    | (GDT)    | (MGD)   | CAPACITY | (MGD)   | CAPACITY |  |  |
|  |     |       |                                  |          |         |          |         |          |         |          | (305)296-5621                            |  |
| Schooner Condo's   | ê   | 49.3  | 605 Sombrero Boulevard           | Marathon | 22      | 5.0      | 0.00353 | 70.60%   | 0.00257 | \$1.40%  | Paul Kenson                              | 1.0 / 5.6  |
|  |     |       |                                  |          |         |          |         |          |         |          | (305)743-3585                            |  |
| Spainsh Galleon Condo  | ₹   | 49.5  | 1115 Sombrero Boulevard Marathon | Marathon | 80      | 5.0      | 0.00472 | 94.40%   | 0.00300 | 800.09   | Luther Kochler                           | 2.0 / 4.0  |
|  |     |       |                                  |          |         |          |         |          |         |          | (305)743-5104                            |  |
| TRACMING WEST CONDO  | 7 4 | 49.3  | 5301 Ocean Terrace               | Marathon | 28      | 6.4      | 0.00193 | 30.16%   | 0.00164 | 25.62%   | Leo Basshand                             | 9'91/9'1   |
|  | 1   |       |                                  |          |         |          |         |          |         |          | (305)743-0256                            |  |
| nuccaneer Lodge  | 7   | 49.5  | 2600 Overseas Highway            | Marathon | 230     | 30.0     | 0.01164 | 38.80%   | 0.00621 | 20.70%   | John Adams                               | 5.8 / 3.3  |
|  | :   |       |                                  |          |         |          |         |          |         |          | (305)743-9071                            |  |
| CUBIA FUMI CONDO   | 7   | 48.9  | 1515 Sombrero Boulevard Marathon | Marathon | 32      | 5.0      | 0.00634 | 126.80%  | 0.00329 | 65.80%   | Tom Murphy                               | 4.0 / 5.6  |
| Marrie Van Bart Cl. 1  | •   | 9 00  |                                  |          |         |          |         |          |         |          | (305)367-2393                            |  |
| Maration Key Beach Club  | 6   | 49.8  | 4590 Overseas Highway            | Marathon | 216     | 30.0     | 0.01950 | 65.00%   | 0.01214 | 40.47%   | elbourne Rappaport Capi                  | 4.8 / 5.7  |
| Section 1  | ŀ   |       |                                  |          |         |          |         |          |         |          | (305)458-8006                            |  |
| Sommero Beach Vallage Util.  | £   | 5.64  | 5 Man O'War Drive                | Marathon | 35      | 5.0      | 0.00179 | 35.80%   | 0.00179 | 35.80%   | Joe Hopps                                | 0.3 / 2.8  |
| Proc far   | 3   | . 03  |                                  |          |         |          |         |          |         |          | (305)743-9265                            |  |
|  | 7   | 1.000 | 13201 Overseas Highway           | Marathon | 268     | 35.0     | 0.03784 | <b>8</b> | 0.02341 | 66.89%   | Donna Johnson                            | 5.1 / 10.7   |
| Cuffeet William Chamine Co.  | 97  | 200   | 0 000                            |          |         |          |         |          |         |          | (305)269-0222                            |  |
| A THE STATE OF THE COLUMN COLU | ç   | 200.4 | DAM Overseas Highway             | Marathon |         | 8.<br>0. | 0.00410 | 51.25%   | 0.00214 | 26.75%   | 26.75% Gulfside Vill Condo Assoc         | 6.3 / 15.8   |
| Harbur Chib South Condo Amore  | Ę   |       |                                  |          |         |          |         |          |         |          | (305)743-0118                            |  |
| ANSA CARRIS CARRO ASSA   | ĵ.  | 49.3  | 423 Sommero Beach Road Marathon  | Marathon | 92      | 0.0      | 0,00114 | 11.40%   | 0.00114 | 11.40%   | Roberta Williamson                       | 1.1 / 2.4  |
| Harbyr House Condo   | S   | 107   |                                  |          |         |          |         |          |         |          | (305)743-0811                            | A CONTRACTOR OF THE PROPERTY AND ADDRESS OF THE PROPERTY A |
|  | 3   |       | 14.17 Sommer Boulevard Marathon  | Marathon | 72      | 2.0      | 0.00129 | 25.80%   | 0.00129 | 25.80%   | Tom Morris                               | 1.2 / 6.4  |
| International House of Parcake   | -   | 95    | $\top$                           | 1        |         | -        |         |          |         |          |  |  |
|  |     | T     | Suway                            | Maraurkm |         | 4,7      | 0.00293 | 62.23%   | 0.00175 | 37.23%   | 37.23% MS Management Sys. Inc. 1.5 / 3.0 | 1.5 / 3.0  |
| The state of the s |     |       |                                  |          |         |          |         |          |         |          | (305)931-5454                            |  |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|                 | <u>~</u>           |         |               |                      |               |                         |               |                             | <u> </u>              |               |                        |   |                        | <u> </u>          |               |                       | _             | <u> </u>                 |               |                   | <u> </u>      | Ī                |               |                       |               |  |
|-----------------|--------------------|---------|---------------|----------------------|---------------|-------------------------|---------------|-----------------------------|-----------------------|---------------|------------------------|---|------------------------|-------------------|---------------|-----------------------|---------------|--------------------------|---------------|-------------------|---------------|------------------|---------------|-----------------------|---------------|--|
|                 | BOD / TSS          |         |               | 0.9                  |               | 10.1                    |               | 8 =                         | 9.9                   |               | 91/                    | - | 8.9                    | 5.3               |               | 5.5                   |               | 6.1                      |               | 1 5.6             |               | 10.6             |               | 15.0                  |               | 5 2 2                                      |
|                 | BOD                |         |               | 4.7 / 6.0            |               | 5.4 / 10.1              |               | 1.0 / 11.8                  | 4.9 / 6.6             |               | 0.9                    |   | 9.0 / 8.9              | 1.4 / 5.3         |               | 7.5 / 5.5             |               | 2.4 / 1.9                |               | 0.3 /             |               | 7.2 / 10.6       |               | 39 / 150              |               | 24.6                                       |
|                 | RESPONSIBLE ENTITY | PHONE   |               | Fred Bohmker         | (305)743-4589 | Jim Simons              | (305)743-3505 | Milford Tesner              | Victor Demaras        | (305)743-3585 | Jack Zito              |   | C/O Isnald Plaza Mgmt. | Thomas Wright     | (305)743-6565 | Lamar Liddle          | (305)743-6561 | Earl Jacck               | (305)743-5969 | G.O. Boston       | (305)743-3513 | R.B. Howard      | (305)422-4070 | A.T. Parson, Jr.      | (904)737-1245 | SI And Danash. Enterprised for 34 C / CC 7 |
|                 | % OF               | DESIGN  | CAPACITY      | 17.88%               |               | 18,68%                  |               | 32.13%                      | 43.95%                |               | 32.71%                 |   | 50.93%                 | 35.67%            |               | 36.53%                |               | 16.67%                   |               | 35.80%            |               | 73.44%           |               | 40.93%                |               | 1007 13                                    |
| AVERAGE         | ONTHI.             | FLOW    | (MGD)         | 0.00143              |               | 0.01121                 |               | 0.00257                     | 0.00879               |               | 0.00157                |   | 0.00764                | 0.00107           |               | 0.00621               |               | 0.00050                  |               | 0.00179           |               | 0.01836          |               | 0.00614               |               | 10 000 00000                               |
|                 | <b>₹</b> 0F        | DESIGN  | CAPACITY      | 36.13%               |               | 27.98%                  |               | 32.13%                      | 77.80%                |               | 32.71%                 |   | 86.47%                 | 62.33%            |               | 70.88%                |               | 89.33%                   |               | 47.20%            |               | 144.36%          |               | 40.93%                |               | 70 900                                     |
| AVERAGE<br>PEAK | DAILY              | FLOW    | (MGD)         | 0.00289              |               | 0.01679                 |               | 0.00257                     | 0.01556               |               | 0.00157                |   | 0.01297                | 0.00187           |               | 0.01205               |               | 0.00268                  |               | 0.00236           |               | 0.03609          |               | 0.00614               |               | 100  |
|                 | DESIGN             | CAP.    | (LCD)         | 8.0                  |               | 0.09                    |               | 8.0                         | 20.0                  |               | 4.8                    |   | 15.0                   | 3.0               |               | 17.0                  |               | 3.0                      |               | 5.0               |               | 25.0             |               | 15.0                  |               |  |
|                 |                    | SERVICE | POP.          | 99                   |               |                         |               |                             | <b>20</b>             |               | 48                     |   | 150                    | 20                |               | 144                   |               |                          |               | 40                |               |                  |               | 256                   |               | 061  |
|                 |                    |         | KEY           | Marathon             |               | Marathon                |               | Marathon                    | Marathon              |               | Marathon               |   | Marathon               | Marathon          |               | Marathon              |               | Marathon                 |               | Marathon          |               | Marathon         |               | Marathon              |               | Monthon                                    |
|                 |                    |         | SITE LOCATION | 9 Sombrero Boufevard |               | 11600 - Ist Avenue      |               | 15 Sombrero Boulevard       | 19 Sombrero Boulevard |               | 303 Sombrero Boulevard |   | 5561 Overseas Highway  | 489 - 63rd Street |               | 6800 Overseas Highway |               | 2275 Anglers Drive       |               | 389 Anglers Drive |               | US I             |               | 6099 Overseas Highway |               | 120 Combron Door board Marathon            |
|                 |                    |         | M.M           | 20.1                 |               | 50.2                    |               | 20.0                        | 49.9                  |               | 49.6                   |   | 50.2                   | 9.09              |               | 20.6                  |               | 51.0                     |               | 808               |               | 50.9             |               | 51.0                  |               | 40.7                                       |
|                 | MAP                | REF     | *             | 52                   |               | 53                      |               | 2                           | 55                    |               | %                      |   | 2                      | <b>%</b>          |               | 8                     |               | æ                        |               | <u>5</u>          |               | 62               |               | 63                    |               | 2  |
|                 |                    |         | SITE NAME     | Island Club Condo    |               | Key Lime Condo (Resort) |               | Marathon Country Club Conto | Symbreto Resort       |               | Symbrero Ridge Condo   |   | K-Mart Shopping Center | Lucy Apartments   |               | The Reef at Marathon  |               | Captain's Quarters Condo |               | Coral Club Condo  |               | Howard Johnson's |               | Key RV Park           |               | Manufact Manue Marring Bone                |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

| A SALA CALLED AND A SALA CALLE |     |      |                             |              |            |        | AVERAGE  |          |          | ,        |                                  |             |
|--|-----|------|-----------------------------|--------------|------------|--------|--|----------|----------|----------|----------------------------------|-------------|
|  |     |      |                             |              |            |        | PEAK   |          | AVERAGE  |          |                                  |             |
|  | MAP |      |                             |              |            | DESIGN | DAILY  | % OF     | ONTHL    | % OF     | RESPONSIBLE ENTITY               | BOD / TSS   |
|  | REF |      |                             |              | SERVICE    | CAP    | FLOW   | DESIGN   | FLOW     | DESIGN   | PHONE                            |             |
| SITE NAME  | *   | MM   | SITE LOCATION               | KEY          | POP.       | (TGD)  | (MGD)  | CAPACITY | (MGD)    | CAPACITY |                                  |             |
|  |     |      |                             |              |            |        |  |          |          |          | (501)723-6712                    |             |
| Perry's Restaurant   | 53  | 51.1 | 6900 Overseas Highway       | Marathon     |            | 4.0    | 0.00273  | 68.25%   | 0.00171  | 42.75%   | 42.75% G. Arvanitus & L. Bouzian | 1.9 / 4.4   |
|  |     |      |                             |              |            |        |  |          |          |          |                                  |             |
| USCG Station   | 8   | 51.0 | 1800 Overseas Highway       | Marathon     |            | 2.5    | 0.00470  | 188.00%  | 0.00229  | 91.60%   | J. M. Sherman                    | 7.5 / 8.5   |
|  |     |      |                             |              |            |        |  |          |          |          | (305)350-5661                    |             |
| 1223 111   | 29  | 52.1 | 111 Street & US 1           | Marathon     | <b>2</b> 6 | 5.0    | 0.00241  | 48.20%   | 0.00100  | 20.00%   | Bobbie Erickson                  | 8.2 / 10.8  |
|  |     | _    |                             |              |            |        |  |          |          |          | (305)743-3330                    |             |
| Scawatch Condo   | æ   | 53.2 | US 1 & Richard Street       | Marathon     |            | 0.0    | 0.00807  | 20.18%   | 0.00421  | 10.53%   | John Armsby                      | 17.3 / 2.2  |
|  |     |      |                             |              |            |        |  |          |          |          |                                  |             |
| Wendy's Restaurant   | 8   | 53.2 | 5150 Overseas Highway       | Marathon     |            | 4.0    | 0.00475  | 118.75%  | 0.00243  | 60.75%   | L. Lynch                         | 10.7 / 9.3  |
|  |     |      |                             |              |            |        |  |          |          |          | (305)973.3444                    |             |
| Winn-Dixie Plaza   | 2   | 52.9 | 52.9 11010 Overseas Highway | Marathon     | 22         | 8.5    | 0.00879  | 103.41%  | 0.00793  | 93.29%   | Alan Schmitt                     | 10.9 / 10.1 |
|  |     |      |                             |              |            |        |  |          |          |          | (305)743-5181                    |             |
| Honelish Tower   |     | 23.8 | 2000 Coco Plum Drive        | Coco Plum Bc |            | 20.0   | 0.01405  | 28.10%   | 0.00989  | 19.78%   | Wm. Trutter                      | 6.2 / 9.7   |
| Treasure Cay Condo   | £   | 3    | 130 Com Diam Dain           | 2            |            |        |  |          |          |          |                                  |             |
| can come   | 2   |      | T                           | Cuco rium Bc |            | 2      | 0.037209   | 40.80%   | 0.00086  | 17.20%   | Edward Hall                      | 7.8 / 4.3   |
| Coco Plum Beach Apartments   | 7,1 | 518  | 105 Avenue D                | 1000         |            | -      | 0000   |          |          |          |                                  |             |
|  |     |      | TO THOUSE D.                | CUXU THUM DC |            | 6.3    | DE NOTE OF THE PERSON OF THE P | ¥1       | 0.0049.3 | 59.40%   | Lee P. Johnson                   | 5.3 / 7.6   |
| Royal Plum Condo   | 74  | 55.0 | 133 Coco Plum Drive         | Coco Plum Bc | 20         | 0.01   | 0.00798  | 79.80%   | 0.00457  | 45.70%   | I ea Pinnin                      | 15/06       |
|  |     |      |                             |              |            |        |  |          |          |          | (305)289-1102                    |             |
| Chean Motel & TP   | 7.  | S8.1 | Route 1, Box 528            | Marathon     | 200        | 15.0   | 0.00164  | 10.93%   | 0.00100  | 6.67%    | Robert Freig                     | 8.0 / 3.0   |
| July Roper Trailer Park  | *   | 50.1 | Posts   Der K76             | 1            | 18         |        | 100  |          |          |          |                                  |             |
| The state of the s |     |      | Model 1, Box 323            | Marathon     | 007        | 20.0   | 10,010   | 63.37%   | 0.01129  | 37.63%   | David Jackson                    | 5.9 / 13.5  |
|  |     |      |                             |              |            |        |  |          |          |          | (305)289-0404                    |             |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|  |         |       |                              |               |         |        | AVERAGE  |                 |           |          |                    |             |
|--|---------|-------|------------------------------|---------------|---------|--------|----------|-----------------|-----------|----------|--------------------|-------------|
|  |         |       |                              |               |         |        | PEAK     |                 | AVERAGE   |          |                    |             |
|  | ΔΥ<br>Σ |       |                              |               |         | DESIGN | DAILY    | % OF            | ONTHE     | %<br>OF  | RESPONSIBLE ENTITY | 231.7 000   |
|  | REF     |       |                              |               | SERVICE | CAP.   | FLOW     | DESIGN          | FLOW      | DESIGN   | PHONE              |             |
| SHENAME  | *       | _     | SITE LOCATION                | KEY           | POP.    | (GDI)  | (MGD)    | CAPACITY        |           | CAPACITY |                    |             |
| Hank s Cay Resent  |         |       | 61.0 US 1, Utility Island    | Duck          | 2000    | 80.00  | 0.06165  | 123 300         | T         | 20.75    |                    |             |
|  |         |       |                              |               |         |        |          | 2000            | 0.000.0   | 27.12%   | Donald Johnson     | 5.2 / 3.6   |
| Long Key Ocean Bay Condo   | *       | 5 59  | P.O. Boy 403                 | 1000          |         | 1      |          |                 | - 1       |          | (305)785-4555      |             |
|  |         | 1     |                              | Lung          | 2       | 2      | 0.00350  | 20.03           | 0.00107   | 15.29%   |                    | 8.0 / 5.0   |
| Outdoor Resort's @ Long Kon  | ۶       | 1     | 10 0 0 0 0                   |               |         |        |          |                 |           |          | (305) 664-8106     | . 1         |
| Second second second   |         |       | US 1 @ Mile Marker 65.5 Long | Swo           |         | 0.09   | 0.04873  | 81.22%          | 0.02893   | 48.22%   | Fred Dichi         | 87/63       |
| Long Key State Park #1   | S       | \$ 63 | DO 00- 776                   |               | 1       |        |          |                 |           |          | (305)664-4860      |             |
|  | 3       | 2.70  | 1.C. DUA 170                 |               | 8       | 2.6    | 0.00234  | ¥00.06          | 0.00083   | 31.92%   | Ney Landrum        | 1.1 / 1.4   |
| One Key State Park #2  | 6       | 2.27  | 700 - 100                    |               |         |        |          |                 |           |          |                    |             |
| THE THE CONTRACTOR   | 5       | 0'/0  | r.U. B0X //6                 | Long          | 8       | 2.6    | 0.00240  | 92.31%          | 0.00100   | 38.46%   | Ney Landrum        | 03/56       |
| Cong Key State Park #3   | 8       | A (3  | D O Bos 176                  |               | -       | ļ      |          |                 |           |          |                    |             |
|  | 5       | 2.70  | . O. DOA 7/0                 | 200           | 8       | 2.6    | 0.00248  | 95.38%          | 0.00100   | 38.46%   | Ney Landrum        | 0.4 / 3.6   |
| Fiesta Kev KOA   | 83      | 70.0  | OF 1. 0 1431.                |               |         |        |          |                 |           |          |                    |             |
|  | 3       |       | CO 1 (th Mile rost /U        | FICKIA        | 88      | 46.0   | 0.05596  | 121.65%         | 0.03079   | 66.93%   | Charles Harris     | 10.0 / 10.5 |
| Kingsail Resort  | 2       | 200   | 7050 Owerses High            |               |         | ,      |          |                 | -         |          | Ī                  |             |
|  |         | 200   | CVCINCAS MIGHWAY             | Maraunon      |         | 3.3    | 0.00299  | 30.61%          | 0.00171   | 51.82%   | John Divine        | 14/62       |
| Calcosa Cove Marina  | 85      | 73.1  | Douts   Dec 0484             |               |         |        |          |                 |           |          | (305)743-6839      |             |
|  | š       |       | MARIE 1, DUX 04IV            | Islanceada    | 25      | 25.0   | 0.00796  | 31.84%          | 0.00)44.3 | 17.72%   | Herman Hicton      | 1.4 / 5.4   |
| Sandy Point Conto  | 2       | 74.5  | OR Costs Braus Daire         | 7             |         |        |          |                 |           |          | (305)664-8798      |             |
| The second secon |         |       |                              | C. Matecumine |         | 3.3    | 0.0000   | 29.09%          | 0.00007   | 2.12%    | E.S. Corlett III   | 1.0 / 4.8   |
| Papa Joe's Restaurant  | 8,      | 707   | 11C 1 Mile Marker 70 7       |               | - 1     |        |          | - [             |           |          | (305)377-8931      |             |
|  |         |       | CO 1, Pint Pint RG 17.7      | C. Maiccumic  | BZ      |        | 0.00492  | 49.20%          | 0.00277   | 27.70%   | Patricia Gehrkins  | 1.7 / 3.9   |
| Mateeninhe Resort (Indian Key)   | ž       | 76.5  | 76761 Overseas Bighuan       |               |         |        |          | - 1             |           |          | (305)644-8756      |             |
|  |         |       | TOTAL OTCINENT HIGHWAY       | L. Matecumpe  |         | 0,01   | 0.000869 | 86.90%          | 0.00350   | 35.00%   | Tammy Macomber     | 8.5 / 5.4   |
| Aufman Construction Co.  | \$      | 080   | 68.0 6799 Overseas Hinhway   | Manufacture   |         | 9      |          |                 |           | -        | (305)644-8801      |             |
|  |         |       |                              | Walada II     |         | E'A    | 17(3)(1) | 94.67% 0.IXXDSR | O.CKNOSR  | 77.33%   | James Alrtman      | 7.4 / 6.5   |
|  |         |       |                              |               |         |        |          |                 |           |          |                    |             |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

| The state of the s |          | *************************************** |                         |              |          |        | AVERAGE |          |         |          | ************************************** |  |
|--|----------|---|-------------------------|--------------|----------|--------|---------|----------|---------|----------|--|--|
|  |          |   |                         |              |          |        | PEAK    |          | AVERAGE | -        |  |  |
|  | MAP      |   |                         |              |          | DESIGN | DAILY   | % OF     | ONTHL   | % OF     | RESPONSIBLE ENTITY                     | BOD / TSS  |
|  | REF      |   |                         |              | SERVICE  | CAP.   | FLOW    | DESIGN   | FLOW    | DESIGN   | PHONE                                  |  |
| SITE NAME  | *        | M.M.                                    | SITE LOCATION           | KEY          | POP.     | (GDI)  | (MGD)   | CAPACITY | (MGD)   | CAPACITY |  |  |
|  |          |   |                         |              |          |        |         |          |         |          | (305)745-5984                          |  |
| Occan 80   | ક્ર      | 80.1                                    | US 1, Mile Marker 80    | Islamorada   | 250      | 25.0   | 0.02731 | 109.24%  | 0.01393 | \$5.72%  | Claire Collen                          | 9.3 / 9.3  |
| **************************************   |          |   |                         |              |          |        |         |          |         |          | (305)644-8861                          |  |
| The Palms of Islamorada  | 91       | 80.4                                    | 79901 Overseas Highway  | Islamorada   | 300      | 20.0   | 0.00875 | 43.75%   | 0.00542 | 27.10%   | J. Vroom                               | 1.4 / 5.0  |
|  |          |   |                         |              |          |        |         |          |         |          | (305)644-9647                          |  |
| Sea Gulls Condo  | 92       | 79.9                                    | 100 Wrenn Street        | Plantation   |          | 17.5   | 0.00944 | 53.94%   | 0.00850 | 48.57%   | Home Owners Assoc.                     | 1.3 / 9.2  |
|  |          |   |                         |              |          |        |         |          |         |          | (305)852-8018                          | And the second control of the second control |
| Breezy Palm Resort Motel   | 8        | 80.1                                    | US 1, Mile Marker 80.1  | Islamorada   | 25       | 15.0   | 0.01190 | 79.33%   | 0.00614 | 40.93%   | Reyond Ketay                           | 3.1 / 10.5   |
|  |          |   |                         |              |          |        |         |          |         |          | (305)664-2361                          |  |
| La Siesta Resort   | 8        | 80.2                                    | US 1                    | Islamorada   |          | 12.5   | 0.00562 | 44.96%   | 0.00246 | 19.68%   | Carl Lindback                          | 1.3 / 4.1  |
|  |          |   |                         |              |          |        |         |          |         |          | (305)664-2132                          |  |
| Fisherman's Kettle Restaurant  | 28       | 80.9                                    | Route 1, Box 110B       | Islamorada   | 130      | 15.0   | 0.00085 | 5.67%    | 0.00055 | 3.67%    | Norma Marrin                           | 7.6 / 6.1  |
| THE PERSON NAMED IN COLUMN TO SERVICE AND ADDRESS OF THE PERSON NAMED IN COLUMN TO SE |          |   |                         |              |          |        |         |          |         | ·        | (305)664-4887                          |  |
| Hay Colony Villas  | 97       | 81.5                                    | US Highway 1            | L. Matecumbe | 95       | 0.0    | 0.00122 | 20,33%   | 0.00054 | 9.00%    | Hamfin Beattie                         | 0.4 / 1.2  |
|  |          |   |                         |              |          |        |         |          |         |          | (803)288-8706                          |  |
| Weerly's Lange   | 88       | 81.9                                    | US I @ Mile Marker 81.9 | Islamorada   | 33       | 33     | 0.00269 | 81.52%   | 0.00114 | 34.55%   | Robert Buck                            | The control of the co |
| 7 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4  | 1        | _                                       |                         |              |          |        |         |          |         |          | (305)843-2535                          |  |
| C heera Lodge  | \$       | 82.1                                    | US I @ Mile Marker 81   | Islamorada   | <u>8</u> | 30.0   | 0.03486 | 116.20%  | 0.02285 | 76.17%   | Tom Zeisel                             | 1.8 / 5.1  |
|  | 1        |   |                         |              |          |        |         |          |         |          |  |  |
| Petican Palm Trailer Park  | <u> </u> | 82.9                                    | P.O. Box 1262           | Islamorada   | 75       | 7.5    | 0.00362 | 48.27%   | 0.00208 | 27.73%   | Olivia Shelley                         | 2.1 / 6.3  |
|  |          |   |                         |              |          |        |         |          |         |          | (305)644-2633                          |  |
| Carrixcan Sunsci Inn   |          | 82.4                                    | P.O. Box 269            | Islamorada   | 200      | 30.0   | 0.00765 | 25.50%   | 0.00369 | 12.30%   | Richard Zzie                           |  |
| We will be a second of the sec |          |   |                         |              |          |        |         |          |         |          | (305)664-4632                          |  |
| Lorelei Restauram  | 102      | <b>R</b> 2.1                            | Madiera Road            | Islamorada   | 8        | 7.5    | 0.00704 | 93.87%   | 0.00429 | 57.20%   | D. Hawley                              | 1.9 / 7.2  |
|  |          |   |                         |              |          |        |         |          |         |          | (305)661-8019                          |  |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|                          |                 | ~                      | _             | ,                 | <del></del>            | ,  |                                    |                                       | _               | <del>, .</del>                     |   | <del></del>                      |               | -س                     |               |                        |               |                            |                          |  |                        |               | *-                   |   |                                |
|--------------------------|-----------------|------------------------|---------------|-------------------|------------------------|--|------------------------------------|---------------------------------------|-----------------|------------------------------------|---|----------------------------------|---------------|------------------------|---------------|------------------------|---------------|----------------------------|--------------------------|--|------------------------|---------------|----------------------|---|--------------------------------|
| BOD / TSS                |                 | 77/64                  |               | 2.0 / 5.4         |                        | 1.4 / 5.7  |                                    | 1.6 / 4.2                             |                 | 1.3 / 3.4                          |   | 1.5 / 3.7                        |               | 1.8 / 5.9              |               | 2.3 / 4.1              |               | 6.1 / 8.0                  | 1.3 / 3.2                |  | 14 / 3.2               |               | 1.6 / 3.0            |   | 1.3 / 2.2                      |
| RESPONSIBLE ENTITY       | PHONE           | Hans Restriccia        | (305)664-3681 | John Ritchie      |                        | Pieretti Livio   | (305)664-4803                      | Christopher Sandry                    | (305)664-4662   | Joseph Roth                        | (305)664-2321                           | 33.95% Holiday Inn Resort/Marina | (305)664-2321 | Cathy Salvatory        | (305)664-4435 | B.C. Sandbar Inc.      | (305)664-4929 | Frank Froemling            | B.M. Vukovich            | (305)730-2000  | Civil Enginecring Unit | (305)536-5661 | Bob Blandford        |   | Joseph R. Oulter               |
| % OF                     | DESIGN          | 53.80%                 |               | 20.28%            |                        | 22.67%   | 7.00                               | 36.13%                                |                 | 31.55%                             |   | 33.95%                           |               | \$0.27%                |               | 13.10%                 |               | 5.27%                      | 19.47%                   |  | 37.20%                 |               | 27.85%               |   | 13.26%                         |
| AVERAGE<br>ONTHE         | FLOW            |                        |               | 33.44% 0.00507    |                        | 0.00408  |                                    | 0.002/1                               |                 | 0.00631                            |   | 0.01358                          |               | 0.00377                |               | 0.00131                |               | 0.00079                    | 0.00146                  |  | 0.00186                |               | 0.00557              |   | 24.09% 0.00464                 |
| <b>\$</b> 0£             | DESIGN          | 112.40%                |               | 33.44%            |                        | 37.83%   | 2000                               | R/7.50                                |                 | 63.10%                             |   | 66.05%                           |               | 100.53%                |               | 20.00%                 |               | 11.20%                     | 34.40%                   |  | 71.40%                 |               | 41.45%               |   | 24.09%                         |
| AVERAGE<br>PEAK<br>DAILY | FLOW (MGD)      | 0.00562                |               | 0.00836           | 10,000                 | 0.03.081   | 00000                              | 704477                                |                 | 0.01262                            |   | 0.02642                          |               | 0.00754                |               | 0.00200                |               | 0.00168                    | 0.00258                  |  | 0.00357                |               | 0.00829              |   | 0.00843                        |
| DESIGN                   | CAP.            | 5.0                    |               | 25.0              | 501                    | 0.61   | 7.6                                | ?                                     |                 | 200                                |   | 40.0                             |               | 7.5                    |               | 0.01                   |               | 15.0                       | 7.5                      |  | 2.0                    |               | 20.0                 |   | 35.0                           |
|                          | SERVICE<br>POP. |                        |               |                   |                        |  | 73                                 | \$                                    |                 | 200                                |   | 360                              |               | \$                     |               |                        |               | 2                          | <b>8</b>                 |  | 38                     |               |                      |   | 382                            |
|                          | KEY             | Islamorada             |               | Islamorada        | fortuna de             | RDR DURING   | felomorada                         | 1 STEEL STEEL STEEL                   |                 | Islamorada                         |   | Windley                          |               | Windley                |               | Windley                |               | Islamorada                 | Windley                  |  | Islamorada             |               | Plantation           |   | Islamarada                     |
|                          | SITE LOCATION   | 82749 Overseas Highway |               | 83201 Old Highway | IIC & Mile Marker 92 4 |  | P.O. Ros 900                       | , , , , , , , , , , , , , , , , , , , |                 | US I @ Mile Marker 84.2 Islamorada |   | US I @ Mile Marker 84.5          | 7             | 84457 Overseas Highway | Т             | US 1, Mile Marker RS.5 |               | US 1, Mile Marker 85.5     | 84961 Overseas Highway   |  | 183 Palermo Drive      |               | Old S.K. 4A          |   | 87.0 Over Seas Highway         |
|                          | Σ               | 82.5                   |               | 83.1              | 21.0                   |  | 836                                | 200                                   | ć               | 24.7                               |   | 84.2                             |               | 84.4                   |               | 200                    | 1             | 65.5                       | 62.5                     |  | K5.7                   | 1             | 97/8                 | 5 | 8/70                           |
| MAP                      | REF             | Ē                      |               | 폴                 | š                      | I  | 3                                  |                                       | į               |                                    |   | ŝ                                | 1             | 8                      |               | =                      |               | Ξ                          | 7                        |  |                        |               | 4                    | 1 | 3                              |
|                          | SITE NAME       | Рету's Inn             |               | Beacon Reef Condo | Cotal Grill Restaurant | ALL THE REAL PROPERTY OF THE P | Chesapeake Motel of Whale Harb 106 |                                       | Howard Johnson! | Tioward Johnson S                  | *************************************** | HOMIGAY ISIC KCSON               |               | l'clican Cove Resort   |               | O. C. Sand Bar         |               | Errk S Floating Restaurant | windicy Key Trailer Park | The state of the s | ( )St. ( ) Station     |               | rantation by the sea | 7 | Plantation Yachi Harbor Resort |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|  |     |      |                        |            |               |        |         |          |         |          | Verified 1.77                   |            |
|--|-----|------|------------------------|------------|---------------|--------|---------|----------|---------|----------|---------------------------------|------------|
|  |     |      |                        |            |               |        | AVERAGE |          |         |          |                                 |            |
|  |     |      |                        |            |               |        | PEAK    |          | AVERAGE |          |                                 |            |
|  | MAP |      |                        |            |               | DESIGN | DAILY   | % OF     | ONTHE   | % OF     | RESPONSIBLE ENTITY              | BOD / TSS  |
|  | REF |      |                        | -          | SERVICE       | CAP.   | FLO₩    | DESIGN   | FLOW    | DESIGN   | PHONE                           |            |
| SITENAME   | *   | M.M. | SITE LOCATION          | KEY        | POP.          | (GDD)  | (MGD)   | CAPACITY | (MGD)   | CAPACITY |                                 |            |
| The state of the s |     |      |                        |            |               |        |         |          |         |          | (305)852-2381                   |            |
| Sen Breeze Trailer Park  | 116 | 87.2 | US 1, Mile Marker 87.2 | Islamarada | 50            | 7.5    | 0.00365 | 48.67%   | 0.00223 | 29.73%   | Angel Ham Sixto                 | 3.9 / 28.2 |
| A A A A A A A A A A A A A A A A A A A  |     |      |                        |            |               |        |         |          |         |          | (305)667-8265                   |            |
| Executive Bay Club   | =   | 87.0 | US 1, Mile Marker 87   | Islamarada | <del>\$</del> | 20.0   | 0.01725 | 34.50%   | 0.01075 | 21.50%   | Mike Carnon                     | 1.9 / 3.9  |
|  |     |      |                        |            |               |        |         |          |         |          | (305)852-3246                   |            |
| Comsi Harbor Club  | 118 |      | Old State Road         | Islamarada |               | 15.0   | 0.00825 | \$5.00%  | 0.00500 | 33.33%   | Le Harris                       | 1.2 / 5.7  |
|  |     |      |                        |            |               |        |         |          |         |          | (305)852-3246                   |            |
| Futura Yacht Club  | 119 |      | 88540 Overseas Highway | Tavernier  |               | 20.0   | 0.01589 | 79.45%   | 0.01414 | 70.70%   | Peter Robustelli                | 1.6 / 5.3  |
| The state of the s |     |      |                        |            |               |        |         |          |         |          | (305)694-4577                   |            |
| Mariner's Hospital   | 120 |      | 50 High Point Road     | Tavernier  |               | 40.0   | 0.03207 | 80.18%   | 0.03007 | 75.18%   | 75.18% Keys Hospital Foundation | 2.0 / 2.7  |
|  |     |      |                        |            |               |        |         |          |         |          |                                 |            |
| Summer Sea Condo   | 121 | 88.5 | 88500 Overseas Highway | Tavernier  | 344           | 26.0   | 0.02130 | 81.92%   | 0.01886 | 72.54%   | Gail Jules                      | 1.3 / 3.5  |
|  |     |      |                        |            |               |        |         |          |         |          | (305)852-9559                   |            |
| Plantation Key Governmental Co.  | 122 |      | 2 High Point Road      | Tavernier  |               | 10.0   | 0.00725 | 72.50%   | 0.00657 | 65.70%   | Monroe County B.C.C.            | 1.2 / 3.8  |
|  |     |      |                        |            |               |        |         |          |         | -        | (305)852-2381                   |            |
| Coral Shores High School   | 123 | 0.06 | US 1, Mile Marker 90   | Tavernier  |               | 15.0   | 0.00813 | \$4.20%  | 0.00729 | 48.60%   | A. Henriquez                    | 1.8 / 3.4  |
|  |     |      |                        |            |               |        |         |          | - 1     |          |                                 |            |
| Sunset Acres Mobile Home Park  | 124 |      | 181                    | Tavemier   |               | 15.0   | 0.00804 | \$3.60%  | 0.00736 | 49.07%   | Marvin Rhodes                   | 1.6 / 5.6  |
|  |     |      |                        |            |               |        |         |          | - 1     |          |                                 |            |
| Plantation Key Elementary Schoo 125  | 125 |      | 100 Lake Street        | Тачетіст   |               | 20.0   | 0.00296 | 14.80%   | 0.00257 | 12.85%   | A. Henriquez                    | 1.1 / 2.1  |
|  |     |      |                        |            |               |        |         |          | ŧ       |          | 1                               |            |
| Turck Enterprise Inc.  | 126 |      | US 1 Mile Marker 90.5  | Tavemier   |               | 5.0    | 0.00248 | 49.60%   | 0.00200 | 40.00%   | Casimer Turek                   | 0.5 / 2.0  |
|  |     |      |                        |            |               |        |         |          |         |          | (305)852-9717                   |            |
| Tavernier Towne Shopping Ctr.  | 127 |      | US 1 at Occan Blvd.    | Tavernier  |               | 50.0   | 0.03921 | 78.42%   | 0.03657 | 73.14%   | For Trust 201                   | 1.8 / 2.4  |
|  |     |      |                        |            |               |        |         |          |         |          | (305)373-0220                   |            |
|  |     |      |                        |            |               |        |         |          |         |          |                                 |            |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

| ,                             |          |      |                             |           |            |        |         |          |                |          | •                      |  |
|-------------------------------|----------|------|-----------------------------|-----------|------------|--------|---------|----------|----------------|----------|------------------------|--|
|                               |          | ~    |                             |           |            |        | AVERAGE |          |                |          |                        |  |
|                               |          |      |                             |           |            | •      | PEAK    |          | AVERAGE        |          |                        |  |
|                               | MAP      |      |                             |           |            | DESIGN | DAILY   | % OF     | ONTHL          | % OF     | RESPONSIBLE ENTITY     | BOD / TSS  |
|                               | REF      |      |                             |           | SERVICE    | CAP.   | FLOW    | DESIGN   | FLOW           | DESIGN   | PHONE                  |  |
| SITE NAME                     | *        | M.M. | SITE LOCATION               | KEY       | POP.       | (GD)   | (MGD)   | CAPACITY | (MGD)          | CAPACITY | -                      | `  |
| Harbor 92 Condo               | 128      |      | 200 Harbor Drive            | Tavenier  | 158        | 10.0   | 0.00654 | 65.40%   | 0.00607        | 60.70%   | C. Stoner              | 1.3 / 6.8  |
|                               |          |      |                             |           |            |        |         |          |                |          | (305)853-3759          |  |
| Silver Shore M.H.P.           | 2        |      | 96.0 US 1 Ocean Side        | Key Largo |            | 83.0   | 0.06586 | 79.35%   | 0.06350        | 76.51%   | Eunice Schroeder       | 1.6 / 5.8  |
|                               |          |      |                             |           |            |        |         |          |                |          | (305)852-5859          |  |
| Driftwood Travel Trailer Park | 8        |      | East of US 1                | Tavemier  |            | 2.0    | 0.00247 | 49.40%   | 0.00193        | 38.60%   | Gail Crawford          | 0.6 / 0.6  |
|                               |          |      |                             |           |            |        |         |          |                |          |                        |  |
| Anchor Condo                  | =        | 92.0 | US 1, Mile Marker 92        | Tavemier  | <u>8</u>   | 9.0    | 0.00509 | 56.56%   | 0.00493        | 54.78%   | Fred Bello             | 2.0 / 4.8  |
|                               |          |      |                             |           |            |        |         |          |                |          | (305)852-3478          |  |
| Blue Water Trailer Park       | 132      |      | Burton Drive                | Tavernier |            | 45.0   | 0.03257 | 72.38%   | 0.02986        | 66.36%   | Morton Feit            | 1.2 / 26   |
|                               | 1        |      |                             |           |            |        |         |          | . t            |          | (305)852-8823          |  |
| Chico Commercial Building     | <u>=</u> |      | Box 94 - Route 1            | Tavernier |            | 2.4    | 0.00141 | 58.75%   | 0.00100        | %L9'17   | Pedro Chico            | 0.4 / 0.6  |
|                               |          |      |                             |           |            |        |         |          |                |          | (305)852-9663          |  |
| Sunset Hammock Condo          | 2        |      | USI                         | Key Largo | <b>8</b> 8 | 20.0   | 0.01414 | 70.70%   | 0.01214        | · 60.70% | Jack Murry             | 1.3 / 5.0  |
|                               | 1        |      |                             |           |            |        |         |          | Í              |          | (305)294-5113          |  |
| Key Largo Ocean Resort        | 135      |      | 94825 Overseas Highway      | Key Largo | 8          | 20.0   | 0.05151 | 73.59%   | 0.04936        | %15'0L   | Key Largo Occan Resort | 1.6 / 8.2  |
|                               |          |      | - 1                         |           |            |        |         |          |                |          | (305)852-3001          | AND THE PROPERTY OF THE PROPER |
| Bullonwood Bay Condo          | 2        |      | 96000 Overseas Hwy, US      | Key Largo |            | 0.0    | 0.03279 | 36.43%   | 0.02557        | 28.41%   | Kelly Bennett          | 1.6 / 7.7  |
| ***                           | 1        | ļ    |                             |           |            |        |         |          |                |          |                        |  |
| The Sheraton                  | 2        | 8.98 | USI                         | Key Largo |            | 0.08   | 0.06721 | 84.01%   | 0.06457        | 80.71%   | KLR Investments, Ltd.  | 1.9 / 4.3  |
|                               |          |      | - 1                         |           |            |        |         |          |                |          | (305)825-9529          |  |
| Key Largo Yacht & Tennis Club | 2        | 97.5 | 97.5 97501 Overseas Highway | Key Largo | \$         | 10.0   | 0.00336 | 33.60%   | 0.00254        | 25.40%   | Francisco Ondarza      | 2,2 / 4,9  |
|                               |          |      |                             |           |            |        |         |          |                |          |                        |  |
| Harborage Condo Corp.         | 139      | 0.86 | 98.0 US I, Mile Marker 98   | Kcy Largo | 74         | 15.0   | 0.00843 | 2.87%    | 0.00821        | \$4.73%  | James Howard           | 1.9 / 47.7   |
|                               |          |      |                             |           |            |        |         |          |                |          | (305)852-3271          |  |
| Rock Harbor Club              | 5        |      | 97652 US 1                  | Kcy Largo | 38         | 35.0   | 0.01446 | 41.31%   | 41.31% 0.01123 | 32.09%   | J.M. Walker            | 20 / 72  |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|  |     |      |                         |           |         |        | AVERAGE<br>PEAK |                     | AVERAGE | •        |                        |            |
|--|-----|------|-------------------------|-----------|---------|--------|-----------------|---------------------|---------|----------|------------------------|------------|
|  | MAP |      |                         |           |         | DESIGN | DAILY           | % OF                | ONTHL   | % OF     | RESPONSIBLE ENTITY     | BOD / TSS  |
|  | REF |      |                         |           | SERVICE | CAP.   | FLOW            | DESIGN              | FLOW    | DESIGN   | PHONE                  |            |
| SITE NAME  | *   | X.   | SITE LOCATION           | KEY       | G       | (1GD)  | (MGD)           | CAPACITY            | (MGD)   | CAPACITY |                        |            |
| And the second s |     |      |                         |           |         |        |                 |                     |         |          | (305)852-3042          |            |
| American Outdoors Key Largo  | 141 |      | Route 1 - Box 384       | Key Largo | 382     | 15.0   | 0.01750         | 116.67%             | 0.01221 | 81.40%   | Richard Harrick        | 1.9 / 6.6  |
| The state of the s |     |      |                         |           |         |        |                 |                     |         |          | (305)852-8054          |            |
| KOA Keys Restaurant  | 142 | 98.0 | S.R. 5 - Mile Marker 98 | Key Largo |         | 7.5    | 0.00586         | 78.13%              | 0.00521 | 69.47%   | Frank Gray             | 3.0 / 4.9  |
| The second secon |     |      |                         |           |         |        |                 |                     |         |          | (305)852-4886          |            |
| Holiday by the Sea Condo   | 143 |      | 300 Ocean Drive         | Key Largo | ×       | 5.0    | 0.00280         | \$6.00 <del>%</del> | 0.00238 | 47.60%   | Holiday By the Seas    | 1.6 / 6.0  |
|  |     |      |                         |           |         |        |                 |                     |         |          |                        |            |
| Paradise Point M.H.P.  | 144 |      | Scaside Avenue          | Key Largo | 14      | 3.2    | 0.00122         | 38.13%              | 0.00100 | 31.25%   | Edward Waser           | 0.4 / 0.7  |
|  |     |      |                         |           |         |        |                 |                     |         |          | (305)852-5000          |            |
| The Landings of Largo  | 145 |      | 98000 Overseas Highway  | Key Largo | 973     | 100.0  | 0.06100         | <b>%00'19</b>       | 0.05823 | \$8.23%  | Ann Peterson           | 1.3 / 3.7  |
|  |     |      |                         |           |         |        |                 |                     |         |          | (305)852-3121          |            |
| Kawama Yacht Club  | 146 |      | 1500 Ocean Bay Drive    | Key Largo | 815     | 80.0   | 0.05636         | 70,45%              | 0.05371 | 67.14%   | Raymond J. Castellanos | 0.01 / 9.1 |
|  |     |      |                         |           |         |        |                 |                     |         |          | (305)220-7366          |            |
| Pizza Hut  | 147 |      | 99020 Overseas Highway  | Key Largo |         | 10.0   | 06900'0         | <b>3</b> 600'69     | 0.00629 | 62.90%   | Pizza Hut, Inc.        | 1.8 / 8.0  |
|  |     |      |                         |           |         |        |                 |                     |         |          |                        |            |
| Occan Divers, Inc.   | 148 |      | Caribean Drive          | Key Largo |         | 7.5    | 0.00342         | 45.60%              | 0.00293 | 39.07%   | Ocean Divers, Inc.     | 0.3 / 3.4  |
|  |     |      |                         |           |         |        |                 |                     |         |          | (305)451-1113          |            |
| Waldorf Plaza Shopping Center  | 149 |      | 100.0 Overseas Highway  | Kcy Largo |         | 30.0   | 0.01457         | 48.57%              | 0.01146 | 38.20%   | Scott Ireland          | 1.7 / 4.4  |
|  |     |      |                         |           |         |        |                 |                     |         |          | (305)891-6806          |            |
| Florida Bay Resort STP   | 150 |      | US I at Ocean Bay Drive | Key Largo | 350     | 35.0   | 0.02579         | 13.69.8F            | 0.02329 | 66.54%   | Raymond Daniel         | 1.4 / 3.0  |
| -  |     |      |                         |           |         |        |                 |                     |         |          | (305)852-9879          |            |
| Best Western Suites  | 151 |      | 201 Ocean Drive         | Kcy Largo | 80      | 20.0   | 0.00712         | 3609°SE             | 0.00654 | 32.70%   | M. Cianciotti          |            |
| the state of the s |     |      |                         |           |         |        |                 |                     | ,       |          |                        |            |
| Holiday Inn  | 152 |      | US 1                    | Key Largo |         | 30.0   | 0.02164         | 72.13%              | 0.01729 | 57.63%   | Randy Goodell          | 1.2 / 7.8  |
|  |     |      |                         |           |         |        |                 |                     |         |          |                        |            |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|  |         |         | % OF RESPONSIBLE ENTITY BOD / TSS | PHONE   | Ļ             | 43.33% Jack Gross 0.3 / 2.1 | 3 | 108.60% Marr Resort Properties 1.4 / 4.4 | + | 38.60% L. Lamborn 0.7 / 2.1   |                   | 35.12% George Eager 2.4 / 23.2 | (305)451-0232 | 60.05% Phillis Martin 1.6 / 6.7 | (305)451-2911 | 50.50% Ira Sochet 1.6 / 5.5  | (305)655-6541 | 63.55% K. Mart Development    | (305)643-5484 | 69.07% Rec. & Parks/J.P. Sommers 1.8 / 2.2 | 63.85% Bill Boston 1.9 / 8.4 | (305)451-1400 | 29.72% Ken Collins 0.6 / 3.0 | (305)451-1522 | 38.08% Gus Boulis        | (305)451-0943  | 30.47% Ian Koblick 1.9 / 7.3 | (305MSI-1139   |   |
|--|---------|---------|-----------------------------------|---------|---------------|-----------------------------|---|--|---|-------------------------------|-------------------|--------------------------------|---------------|---------------------------------|---------------|------------------------------|---------------|-------------------------------|---------------|--|------------------------------|---------------|------------------------------|---------------|--------------------------|--|------------------------------|--|---|
| i  |         | AVERAGE | ONTH                              | FLOW    | (MGD)         | 0.00143                     |   | 0.01629                                  |   | 0.00193                       |                   | 0.02107                        |               | 0.01321                         |               | 0.01515                      |               | 0.01271                       |               | 0.03108                                    | 0.02107                      |               | 0.00107                      |               | 0.00457                  |  | 0.00457                      | _  |   |
|  | ***     |         | <b>₹</b> 0F                       | DESIGN  | CAPACITY      | 57.88%                      |   | 138.07%                                  |   | \$6.60%                       |                   | 46.32%                         |               | 73.36%                          |               | 70.47%                       |               | 81.45%                        |               | 79.16%                                     | 85.94%                       |               | 38.61%                       |               | 56.58%                   |  | 45.93%                       |  |   |
|  | AVERAGE | PEAK    | DAILY                             | FLOW    | (MGD)         | 0.00191                     |   | 0.02071                                  |   | 0.00283                       |                   | 0.02779                        |               | 0.01614                         |               | 0.02114                      |               | 0.01629                       |               | 0,03562                                    | 0.02836                      |               | 0.00139                      |               | 0.00679                  |  | 0.00689                      |  |   |
|  |         |         | DESIGN                            | CAP.    | (dDT)         | 3.3                         |   | 15.0                                     |   | 85                            | ļ                 | 60.0                           |               | 22.0                            |               | 30.0                         |               | 20.0                          |               | 45.0                                       | 33.0                         |               | 3.6                          |               | 12.0                     |  | 15.0                         |  |   |
|  |         |         |                                   | SERVICE | <u>8</u>      | 98                          |   | 112                                      |   | 8                             |                   | 765                            |               |                                 |               |                              |               |                               |               | 3200                                       | <u>8</u>                     |               | જ્ઞ                          |               |                          |  |                              |  |   |
|  |         |         |                                   |         | KEY           | Highway Kcy Largo           |   | Key Largo                                |   | Key Largo                     |                   | Key Largo                      |               | Highway Key Largo               |               | Key Largo                    |               | Key Largo                     |               | Kcy Largo                                  | Key Largo                    |               | Key Largo                    |               | Key Largo                |  | Key Largo                    |  |   |
|  |         |         |                                   |         | SITE LOCATION | 102900 Overscal Highway     |   | 100.0 529 Caribean Drive                 |   | US I                          |                   | US I and Caites Sires          |               | 101.6 101600 Overseas Highway   |               | US 1, Mile Marker 112.5      |               | 101.0 US I, Mile Marker 101.2 |               | P.O. Box 487                               | Overseas Highway 1           |               | 102.0 Overseas Highway       |               | 102050 S. Overses Highwy |  | 51 Shoreland Drive           |  |   |
|  |         |         |                                   |         | M.M.          | 0.00                        |   | 0.00                                     |   | 0.0                           | 3 101             | C.101                          |               | 9.101                           |               | 112.5                        |               | 0.101                         | į             | 102.0                                      | 102.0                        | 40            | 102.0                        |               | 102.5                    |  | 103.4                        |  | L |
|  |         |         | Ŝ                                 | REF     | *             | 153                         |   | 154                                      |   | 155                           | 22.5              | 2                              |               | à                               |               | 2                            |               | 159                           |               | 8  | 9                            | 3             | 79                           |               | <u>e</u>                 |  | Z                            |  |   |
| The state of the s |         |         |                                   | · ·     | SITE NAME     | Lecside Professional Bldg.  |   | Port Largo Villas                        |   | Coastal Waterway Trailer Park | Coluca Coma Bacad | Calusa Camp Result             |               | Cheun's transfrark & Campgr.    |               | Kcy Largo Campground & Marin |               | radewinds/K-Marl Shop. Cht    |               | Coral Reci Stac Park                       | <br>Foward Johnson's         |               | Faranse Pab                  |               | The Quay Restaurant      | The state of the s | Koblick Marine Center        | To the second se |   |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|  |     |        |                              |                   |           |        | AVERAGE<br>Peak |                | AVERAGE |          |                          |             |
|--|-----|--------|------------------------------|-------------------|-----------|--------|-----------------|----------------|---------|----------|--------------------------|-------------|
|  | MAP |        |                              |                   |           | DESIGN | DAILY           | % OF           | ONTHE   | % OF     | RESPONSIBLE ENTITY       | BOD / TSS   |
|  | REF |        |                              |                   | SERVICE   | CAP.   | FLOW            | DESIGN         | FLOW    | DESIGN   | PHONE                    |             |
| SITE NAME  | #   | M.M.   | SITE LOCATION                | KEY               | POP.      | (GDD)  | (MGD)           | CAPACITY       | (MGD)   | CAPACITY |                          |             |
|  |     |        |                              |                   |           |        |                 |                |         |          | (305)451-0101            |             |
| Senior Frijoles Restaurant   | 167 | 6'801  | 103900 B Overseas Hghw       | Key Largo         | 061       | 4.6    | 0.00252         | \$4.78%        | 0.00179 | 38.91%   | Robert C. Story          |             |
|  |     |        |                              |                   |           |        |                 |                |         |          | (305)451-1592            |             |
| Italian Fisherman Restaurant   | 168 | 104.0  | 104.0 10400 Overseas Highway | Key Largo         |           | 15.0   | 0.00000         | 960:00%        | 0.00586 | 39.07%   | John Baimonte            | 2.9 / 5.3   |
|  |     |        |                              |                   |           |        |                 |                |         |          | (305)852-4703            |             |
| Moonbay Condo  | 69  | 104.3  | 104350 Overseas              | Highway Kcy Largo |           | 26.0   | 0.01601         | 61.58%         | 0.01214 | 46.69%   | Ronald Kennedy           | 1.7 / 9.0   |
|  |     |        |                              |                   |           |        |                 |                |         |          | (305)451-0186            |             |
| Tamarino Bay Club, Inc.  | 13  | 104.5  | 10450 Overseas Highway       | Key Largo         |           | 15.0   | 0.00850         | <b>36.67</b> % | 0.00529 | 35.27%   | Don Mummert              | 1.9 / 7.7   |
|  |     |        |                              |                   |           |        |                 |                |         |          | (305)451-1074            |             |
| Kcy Largo Elementary School  | 171 | 105.0  | US 1, Mile Marker 105        | Key Largo         | 675       | 25.0   | 0.01517         | 60.68%         | 0.01257 | \$0.28%  | A. Henriquez             | 1.6 / 6.4   |
|  |     |        |                              |                   |           |        |                 |                |         |          |                          |             |
| Winn Dixie   | 172 | 105.3  | US 1, and Blackwater Dr.     | Key Largo         | 30        | 5.0    | 0.00375         | 75.00%         | 0.00283 | \$6.60%  | Russ Post                |             |
|  |     |        |                              |                   |           |        |                 |                |         |          |                          |             |
| Barefoot Key R.V. Resort   | 173 | 106.0  | 106.0 US 1, Mile Marker 106  | Key Largo         |           | 15.0   | 0.00570         | 38.00%         | 0.00364 | 24.27%   | F. A. Jackson            | 2.0 / 7.0   |
|  |     |        |                              |                   |           |        |                 |                |         |          |                          |             |
| Gilbert's Motel & Marina   | 2   | 106.0  | US 1 at Jewfish Creek        | Key Largo         | 2         | 0.01   | 0.00612         | 61,20%         | 0.00379 | 37.90%   | Paul LaCoursiere         | 1.7 / 6.1   |
|  |     |        |                              |                   |           |        |                 |                |         |          | (305)451-1133            |             |
| The Anchorage Resort   | 175 | 107.5  | US 1, Mile Marker 107.5      | Key Largo         | Q2<br>202 | 10.0   | 0.00790         | 79,00%         | 0.00393 | 39.30%   | Susan Walker             | 5.5 / 8.7   |
|  |     |        |                              |                   |           |        |                 |                |         |          | (305)451-2611            |             |
| Ocean Reef Club (Util, Co.)  | 176 | 12.0   | 31 Occan Reef Drive          | Kcy Largo         | 3532      | 450.0  | 0.24857         | 55.24%         | 0.17450 | 38.78%   | Russell Post             | 5.2 / 6.6   |
|  |     | _      |                              |                   |           |        |                 |                |         |          | (305)367-2611            |             |
| Hamingo STP  | 173 | ₹<br>Ž | Everglades National Park     | Flamingo          | 96        | 0.06   | 0.03171         | 35.23%         | 0.01757 | 19.52%   | Everglades National Park | 3.6 / 2.1   |
|  |     |        |                              |                   |           |        |                 |                |         |          | (305)247-6211            |             |
| Waters Edge Colony Park  | 178 | 5.1    | Laurel and 2 Street          | Stock Island      |           | 7.5    | 0.00825         | 110.00%        | 0.00757 | 100.93%  | Maricta L. Kaszyk        | 36.2 / 55.8 |
| A WARANA MARIA MANAMBANA M |     |        |                              |                   |           |        |                 |                |         |          | (305)296-1709            |             |
|  |     |        |                              |                   |           |        |                 |                |         |          |                          |             |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|  |         |         | SS                 |         |               |                                  |               | Ī                   |               |                               |               |                             |               | Ī                              |               | -                      |               | <u> </u>               | [ <del></del> | Ī                          |               |                                  | <u> </u> |                        | - ·- |                    |               |                          | <u> </u>      | _ |
|--|---------|---------|--------------------|---------|---------------|----------------------------------|---------------|---------------------|---------------|-------------------------------|---------------|-----------------------------|---------------|--------------------------------|---------------|------------------------|---------------|------------------------|---------------|----------------------------|---------------|----------------------------------|----------|------------------------|------|--------------------|---------------|--------------------------|---------------|---|
|  |         |         | BOD / TSS          |         |               | 5.8 / 3.1                        |               | 3.9 / 5.0           |               | 25.5 / 25.8                   |               | 11.2 / 16.2                 |               | 2.3 / 5.5                      |               |                        |               | 1.6 / 3.4              |               | 93/77                      |               | 1.4 / 2.6                        |          | 1.8 / 3.6              |      | 1.2 / 8.0          |               |                          |               |   |
| *  |         |         | RESPONSIBLE ENTITY | PHONE   |               | Thomas Kelly                     | (305)745-3030 | Athanasia Anderson  | (305)743-5597 |                               | (305)743-7137 | William Ortin               | (305)743-3417 | Jim Green                      | (305)743.7099 | N. Baillon & R. Moret  | (201)285.9000 | Ray Shamblum           | (305)664-3681 | Hans Restuccia             | (305)664-3681 | Joseph Roth                      |          | Charles Minges         |      |                    | (305)852-4460 | Doug Douglas             | (305)245-5547 |   |
| ` `  |         | -       | <b>4</b> 0₽        | DESIGN  | CAPACITY      | 11.30%                           |               | 50.67%              |               | 73.43%                        |               | 18.60%                      |               | 6.20%                          |               | 25.00%                 |               | 9.53%                  |               | 16.40%                     |               | 12.30%                           |          | 12.70%                 |      | 4.84%              |               | 31.05%                   |               |   |
|  |         | AVERAGE | ONTHE              | FLOW    | (MGD)         | 0.00113                          |               | 0.00076             |               | 0.00257                       |               | 0.00093                     |               | 0.00031                        |               | 0.00030                |               | 0.00143                |               | 0.00164                    |               | 0.00246                          |          | 0.00254                |      | 0.00121            |               | 0.00621                  |               |   |
|  |         |         | <b>%</b> 0₽        | DESIGN  | CAPACITY      | 18.10%                           |               | \$2.00%             |               | 111.14%                       |               | 23.00%                      |               | 8.00%                          |               | 53.33%                 |               | 22.40%                 |               | 37.50%                     |               | 30.20%                           |          | 25.60%                 |      | 9.32%              |               | 48.15%                   |               |   |
|  | AVERAGE | PEAK    | DAILY              | FLOW    | (MGD)         | 0.00181                          |               | 0.00078             |               | 0.00389                       |               | 0.00115                     |               | 0.00040                        |               | 0.00064                |               | 0.00336                |               | 0.00375                    |               | 0.00604                          |          | 0.00512                |      | 0.00233            |               | 0.00963                  |               |   |
|  |         |         | DESIGN             | CAP.    | (IGD)         | 10.0                             |               | 1,5                 |               | 3.5                           |               | 5.0                         |               | 5.0                            |               | 1.2                    |               | 15.0                   |               | 10.0                       |               | 20.02                            |          | 20.0                   |      | 25.0               |               | 20.0                     |               |   |
|  |         |         |                    | SERVICE | POP.          |                                  |               |                     |               |                               |               |                             |               |                                |               |                        |               |                        |               |                            |               |                                  |          |                        |      |                    |               |                          |               |   |
|  |         |         |                    |         | KEY           | Sugarloaf                        |               | Marathon            |               | Marathon                      |               | Marathon                    |               | Marathon                       |               | L. Matecumbe           |               | Islamorada             |               | stamorada                  |               | Istamorada                       |          | Islamorada             |      | Islamorada         |               | Hy. #240 Key Largo       |               |   |
|  |         |         |                    |         | SITE LOCATION | Overseas Highway MM 20 Sugarloaf |               | 1501 Sombrero Blvd. |               | 35 Sombrero Blvd.             |               | 5230 Overseas Highway       |               | 52.5 11187 Overseas Highway    |               | Overseas Hghwy. MM.76. |               | 80450 Overseas Highway |               | Mile Marker 82.5           |               | P.O. Box 588                     |          | 84977 Overseas Highway |      | State Road 905     |               | 103400 Overseas Hy. #240 |               |   |
|  |         |         |                    |         | X.            | 20.0                             |               | 48.9                |               | 49.6                          |               | 49.8                        |               | 52.5                           |               | 76.5                   |               | 80.5                   |               | 82.5                       |               | 84.9                             |          | 85.0                   |      | 87.8               |               | 103.4                    |               |   |
|  |         |         | MAP                | REF     | *             | 179                              |               | <u>8</u>            |               | æ                             |               | 182                         |               | <b>283</b>                     |               | 184                    |               | 282                    |               | 98                         | _             | £                                |          | <b>88</b>              |      | <u>£</u>           |               | 8                        |               |   |
| The state of the s |         |         |                    |         | SITE NAME     | Mangrove Maria's                 |               | Casa De Los Tres    |               | Sombrero Marina & Dockside Ln |               | Susan's "Wobbly-Crab" Rest. |               | Jim Green Marathon Vet. Clinic |               | Fantasy Harbor Condo   |               | Sand Pebbles           |               | Perry's Seafood Restaurant |               | Hartwr Lights Motel/Holiday Isle |          | Iropical Reef Resort   |      | Occan Harbor Condo |               | North Key Largo Plaza    |               |   |

TABLE 10 - 4
SANITARY SEWER PACKAGED TREATMENT PLANT OPERATIONS REPORT

|                             |     |       |                               |                     |              |        | AVERAGE  |          |                | •              |                              |             |
|-----------------------------|-----|-------|-------------------------------|---------------------|--------------|--------|----------|----------|----------------|----------------|------------------------------|-------------|
|                             |     |       |                               |                     |              |        | LAK<br>K |          | VERACIE        |                |                              |             |
|                             | MAP |       |                               |                     |              | DESIGN | DAILY    | % OF     |                | % OF           | RESPONSIBLE ENTITY BOD / TSS | 80D / TSS   |
|                             | REF |       |                               |                     | SERVICE CAP. | CAP.   | FLOW     | DESIGN   | FLOW           | DESIGN         | PHONE                        |             |
| SITE NAME                   | *   | Σ     | SITE LOCATION                 | KEY                 | <u>8</u>     | (QQL)  | (MGD)    | CAPACITY | (MGD)          | (MGD) CAPACITY |                              |             |
|                             |     |       |                               |                     |              |        |          |          |                |                | (305)451-5570                |             |
| l 'Ossis                    | 192 | 106.7 | 106.7 106690 Overseas Highway | Highway Key Largo   |              | 2.6    | 0.00137  | 52.69%   | 52.69% 0.00086 | 33.08%         | Ignatius Adams               | 0.4 / 0.9   |
|                             |     |       |                               |                     |              |        |          |          |                |                | (305)451-1929                |             |
| Cross Key Marina/Restaurant | 5   | Į.    | 112.5 Murris Avenue           | Cross               |              | 3.0    | 0.00182  | 60.67%   | 60.67% 0.00121 | 40,33%         | Ray Vera                     |             |
|                             |     |       |                               |                     |              |        |          |          |                |                | (305)451-2779                |             |
| Marathon Trailcrama         | 194 |       | 47.9 1571 Overseas Highway    | Marathon            |              | 20.0   | 96900'0  | 34.80%   | 34.80% 0.00440 | 22.00%         | Vincent Alexander            | 31.8 / 34.3 |
|                             |     |       |                               |                     |              |        |          |          |                |                | (305)743-6962                |             |
| The Sanctuary               | 56  | 1000  | 100.0 US 1 & Bay Hammock Dr.  | mmock Dr. Key Largo |              | 0.01   | 0.00621  | 62,10%   | 62,10% 0.00414 | 41.40%         | Harold Kessler               | 1.6 / 5.0   |
|                             |     |       |                               |                     |              |        |          |          |                |                | (305)271-1088                |             |

Table 10.5
Facilities Discharging to Surface Water

| NAME                               | MAP REF |
|------------------------------------|---------|
| Venture Out @ Cudjoe Key           | 15      |
| US Coast Guard Station<br>Marathon | 66      |
| Islamorada                         | 133     |
| USNAS<br>Boca Chica Field          | 7       |
| Waters Edge MHP                    | 178     |
| Fiesta Key KOA                     | 83      |

Source: Florida Health and Rehabilitation Services, 1991

As permits expire, it is necessary for these facilities to come into compliance with current criteria. It becomes more cost effective for smaller facilities to change the method of effluent disposal and most facilities change to a Class V well constructed in accordance with Chapter 17-28 FAC.

There are certain tools available to the DER for establishing compliance or noncompliance with the waste treatment standards. One such tool is the information submitted on the self-monitoring operational reports. The information provided on these reports and monitoring frequency depends on the design capacity and method of effluent disposal.

The DER may also take enforcement action based on its own sample collection activities. This activity is generally combined with their policy of facility inspections at a minimum frequency of once per year.

Effective July 1991, an applicant renewing a permit is required to submit a Capacity Analysis Report. This information will assist the DER in evaluating facility performance as it relates to design capacity.

Currently there are 13 wastewater treatment plants under some kind of enforcement action by DER (see Table 10.6). The first enforcement action that the DER initiates when a facility is found to be in non-compliance is a Warning Notice. Most individuals responsible for the operation of a facility will attempt to solve their differences with DER at this stage. If the differences cannot be resolved, the DER attempts to execute a Consent Order. With a Consent Order, the respondent agrees to compliance issues and schedules. If a Consent Order is not attainable the DER will pursue legal action.

Table 10.6
Facilities Currently under DER Enforcement Action

| NAME                     | MAP REF | STATUS   |
|--------------------------|---------|--|
| Sunset Inn               | 101     | Exceeded effluent limitations CASE RESOLVED              |
| Coconut Grove            | 4       | Did not comply with C.O. DER INITIATED LEGAL PROCEEDINGS |
| Waters Edge MHP          | 178     | Did not comply with C.O. DER INITIATED LEGAL PROCEEDINGS |
| Royal Plum Condo         | 74      | Unauthorized connection CASE RESOLVED                    |
| Little Palm Island       |         | IN COMPLIANCE WITH C.O.                                  |
| Sunshine Key Travel Park | 24      | IN COMPLIANCE WITH C.O.                                  |
| Galaway Bay MHP          | 27      | IN COMPLIANCE WITH C.O.                                  |
| Ocean 80                 | 90      | Signed C.O. in December '91                              |
| Key Haven Utility        | 6       | IN COMPLIANCE WITH C.O.                                  |
| Lorelei                  | 102     | Operating without permit IN PROCESS OF OBTAINING PERMIT  |

Source: Florida Department of Environmental Regulation, 1991

## 10.3 Assessment and Inspection Programs

## 10.3.1 Septic Tank Inspection Program

The septic tank/cesspool inventory being conducted in conjunction with the Comprehensive Plan will provide the database for identifying unregulated and inoperative septic tanks and cesspools for compliance with the provisions of Section 9.5-294(a)(3) of the Monroe County Land Development Regulations. These regulations require that all on-site wastewater treatment facilities be inspected by a licensed contractor or engineer every three years to determine whether or not that facility is meeting performance standards. At the present time, these inspection requirements are not being enforced. In recognition of this HRS has proposed a mandatory septic tank inspection program which would be financed by an assessment on county property taxes. Exempted from this assessment would be those homes and businesses less than three years old, systems which have records of repairs within the last three years, and properties serviced by DER regulated sewage treatment plants. The proposal places the responsibility for conducting the field inspections and followup permitting and inspection for repairs on HRS and the responsibility for data compilation and maintenance on Monroe County. The

main thrust of the proposed program would be the enforcement of regulations related to illegal septic systems and cesspools.

#### 10.3.2 Water Quality Monitoring

The waters of the Florida Keys historically have been considered pristine and unadulterated, but with increasing population and development pressure over the past decade and a half, concern has arisen that water quality is being degraded by development activities. The natural assets of the Florida Keys are the basis of the tourism and fishing industries and are largely dependent upon maintenance of good water quality. Unchecked degradation of water quality would undoubtedly alter marine communities, with unpredictable but probable detrimental effects upon the beneficial uses of nearshore waters. Further deterioration to the point of creating a public health hazard would be catastrophic (CH2M Hill, 1979).

Discharges to surface waters are regulated under Chapters 17-3 and 17-4 of the F.A.C., and cannot depress water quality below specified criteria. The waters of the Florida Keys have been classified as Class III waters with designated uses for recreation, and propagation and management of fish and wildlife. In April 1985 the waters of the Florida Keys were reclassified as Outstanding Florida Waters (OFWs), and as such, their existing ambient water quality may not be degraded as a result of any human activity or discharge.

## A. Previous Water Quality Assessment Programs

The Florida Keys OFW Monitoring Study was conducted in 1985 to collect baseline data on water quality for ambient and artificially created waters within the Florida Keys. A total of 165 stations were sampled from Key Largo to Key West along the Florida Bay side and Atlantic Ocean side of the Florida Keys. Sampling which began January 8, 1985, was concluded February 20, 1985. Due to the extensive surface area of the waters in the Florida Keys (120 miles bayside and 120 miles oceanside) and limited manpower and time available, the number of stations and parameters were kept at a minimum. Monitoring points were equally distributed between bay and ocean to provide uniform coverage. A total of 81 stations (49 ambient and 32 artificial waterways) were monitored along the oceanside of the Florida Keys, while a total of 84 stations (46 ambient and 38 artificial waterways) were sampled along the bayside. Artificial waterways sampled included canals, boat basins and marinas adjacent to trailer parks, single- and multiple-family dwellings, and commercial operations. Ambient stations were located approximately 1/4 mile offshore in most cases with occasional controls located within mangrove creeks.

As the data indicates, all ambient stations monitored in this survey exceed Class III standards. On the other hand, the artificial waterways show varying degrees of degradation. Most artificial waters are impacted by reduced circulation due to excessive depths and the orientation and configuration of the design. This compounds the detrimental influence from uncontrolled stormwater runoff, septic leachate and the accumulation of floating organic debris. All of the factors, as the data supports, degrade the water quality often below existing standards. Future increases in the population adjacent to these waterways will only result in additional degradation. Serious measures would have to be implemented to slow or reverse this trend. The 205-J study completed by DER in 1989 addresses these specific sources, and includes results and recommendations regarding the necessity and feasibility of central collection and secondary treatment of these sources.

In addition, a state-wide summary describes the extent and nature of nonpoint source pollution of surface waters in the Florida Keys Basin as reported by DER in 1989. The basin summary contains a general description of the basin, an estimate of the extent of the assessment (10 percent), and a discussion of specific nonpoint pollution problems in the basin.

Most of the nonpoint source problems reported in the 1989 Report are in the vicinities of Key West and Marathon. In the Key West area, Safety Harbor, Key West Harbor, Garrison Bight, Riviera Canal, and Cow Key Channel are moderately impaired as a result of urbanization, live-aboards, boaters and boat and marina activities. Nutrients, bacteria, oils, grease, habitat alteration, turbidity and odor affect all of those water bodies. Garrison Bight is additionally affected by low dissolved oxygen (DO), sediments, septic tank seepage and declining fisheries. The natural flow through Garrison Bight has been altered by hydrologic modification. Flow alteration is also reported for Key West and Safety Harbors. Landfills on Stock Island are located very close to the water and are sources of sediments and metals which threaten Gulf waters. Landfills similarly threaten Gulf waters near Long Key.

Nonpoint problems in Marathon have not progressed to the high level of impairment apparent in Key West, but threatened conditions are prevalent. Urbanization, septic tank seepage and hydrologic modification (canals) are sources of sediments, nutrients, bacteria, debris, oils and grease. As a result, odor and turbidity problems are increasing, dissolved oxygen and fisheries are declining, and there has been loss of natural habitat.

On Plantation Key, marina activities and septic tank seepage have contributed to the moderate impairment of Tavernier Creek. Nutrients, bacteria, debris, oils and grease are associated with low DO, odors, turbidity, and loss of habitat. Lake Largo on Key Largo is similarly moderately impaired. Surface water in the vicinity of Holiday Isle, a development on Windley Key, is threatened by urbanization.

In addition, a domestic wastewater nutrient study is currently underway in order to determine the impact of secondary treatment plant effluent discharged into Class V injection wells on adjacent surface waters. The subject of the study is a 0.020 MGD extended aeration plant recently built in conjunction with a new development project located in Saddle Bunch Key, called Blue Water RV Park. A total of seven monitoring wells and seven surface water stations will be monitored for various parameters. Monitoring will take place before and after the plant begins operation, for a period of two years, in order to assess whether nutrient enrichment occurs in surface waters adjacent to the boreholes after the treatment plant begins to discharge.

In February 1990, Florida Keys Land and Sea Trust, completed the study, "Ambient Water Quality Assessment in the Middle and Lower Florida Keys During Summer, 1989." This study, supported by the MacArthur Foundation and Monroe County, represents a comprehensive ambient water quality assessment for nearshore waters of the Middle and Lower Florida Keys. The hard data and observations of nearshore nutrient enrichment, algal blooms, coral disease, seagrass epiphytization, hypoxia, and frequent violations of state DO standards throughout nearshore water of the Florida Keys as reported by the Sea and Land Trust study indicates that these waters are not pristine, as generally viewed by the tourist or layman, but in fact stressed by nutrient loading and associated eutrophication. In addition, the study concludes that within Monroe County as a whole, OSDS are the single most

important contributor to nonpoint source loading. These findings underscore a critical need for expanded monitoring efforts to further our knowledge of the extent and nature of degraded nearshore waters.

However, data and assumptions found in the "Ambient Water Quality Assessment in the Middle and Lower Florida Keys During Summer, 1989" and "Final Report on the Effects of On-site Sewage Disposal Systems on Nutrient Relations of Groundwater and Near Shore Waters of the Florida Keys" can only be utilized as generalized material, until verified.

Although a county-wide water quality monitoring program was called for under the "Area of Critical State Concern" designation in 1974 and the Monroe County Comprehensive Plan of 1986, neither Monroe County nor DER has initiated a comprehensive County-wide monitoring program. NOAA has recently embarked on a program through the creation of the National Marine Sanctuary (NMS) to improve water quality within the sanctuary boundaries.

#### B. Future Water Quality Monitoring Needs

The recent designation of the Florida Keys as OFWs alters the format of future water quality monitoring by DER in Monroe County. Rather than simply investigating areas suspected of impact for violations of Class III water quality standards, the DER must measure ambient water quality in order to document future degradation of existing conditions. Although Class III standards still serve as minimum criteria under the OFW classification, any significant reduction of water quality can incur enforcement by DER if sufficient baseline data is available.

The advantage of the OFW designation is that it eliminates the ambiguity of establishing the concentration at which a pollutant becomes detrimental to environmental quality, and instead simply prevents any significant change of existing water quality, regardless of the known or unknown effects of constituent concentrations. A future monitoring study by DER in the Florida Keys must be designed with the understanding that suspected changes in water quality cannot be determined without adequate background or baseline data.

As stated previously, the aim of future monitoring in the Florida Keys should be to document significant degradation of water quality, where "significant" is defined on the basis of adverse impacts on man's beneficial uses of the water. Those beneficial uses, such as swimming, fishing, and diving, are directly or indirectly dependent upon maintenance of a healthy ecosystem.

The Quality Assurance Section of DER is currently in the process of developing Chapter 17-160, F.A.C., titled Quality Assurance. These rules will identify specific quality assurance requirements for all Department programs and activities. In addition, these rules will also define the types of Quality Assurance Plans that must be submitted, and the procedures for obtaining Quality Assurance Plan approval. The QA Section is also revising the document DER Guidelines for Preparing Quality Assurance Plans (DER-QA-001/85) published in 1986, to provide additional information in preparing QA plans for the Department. This document, DER Manual for Preparing Quality Assurance Plans (DER-QA-001/90), is in draft form and pending adoption.

Any and all future monitoring procedures should be approved by the DER and the EPA for compliance with pending Quality Assurance requirements of F.A.C., Rule 17-160 and 40 CFR, Part 136 to ensure that proper quality control guidelines are followed during data collection and reporting.

In its Preliminary Policy Direction for the Comprehensive Plan adopted in February, 1991, the Monroe County Board of County Commissioners adopted policies to link future development decisions to water quality monitoring and to implement the coordination of a monitoring network and map water quality trends on a Geographic Information System. One of the goals of the proposed program is to link specific water quality problems in a given area to specific development activities. The identification of the location of unpermitted septic systems and cesspools will be an important component in tracing point sources of pollution to individual or concentrations of inadequately functioning septic tanks and cesspools once the nearshore water quality monitoring program is implemented.

#### 10.3.3 Resource Management

Continued increase in the number and type of wastewater treatment and disposal systems in Monroe County will inevitably increase concerns for the protection of public health and water quality. Previous sections of this Sanitary Sewer Element have focused on growth management strategies and improved wastewater facilities to correct existing deficiencies and accommodate future demands. Equally important is the need to implement resource management strategies which recognize the reuse of wastewater effluent as a viable resource, and which, through water conservation techniques, effectively reduce the wastestream that results in potential threats to public health and water quality. Through the implementation of revised Land Development Regulations and building codes, and improved public educational efforts, individual and cumulative impacts of sewage treatment and disposal can be reduced.

#### A. Water Conservation

There are three major reasons to emphasize water conservation when developing land for residential, commercial, industrial, or other use. All or only one or two of the reasons may apply to a particular development. All should be given consideration as appropriate to the project. The major reasons are:

- (a) To conserve a valuable resource in its most natural or purest state;
- (b) To lessen or minimize the waste load to a central wastewater treatment facility; and
- (c) To minimize the waste load to on-site wastewater facilities.

By minimizing the quantities of water that are used, wastewater processing becomes an easier, less costly process. Growth moratoriums can be eliminated or slowed by instituting sound water conservation measures when overloaded treatment plants are the cause. This same principle applies to on-site treatment facilities; an overloaded system may still be usable if the volume of wastewater is significantly decreased. In each of these instances, monetary as well as environmental costs are at stake. The building of new treatment plants or the expansion of existing plants when not absolutely necessary becomes a financial burden on a community.

Additional disposal areas required to compensate for overloaded individual on-site systems can also be a costly burden to the homeowner or businessman. If there are too many overloaded systems in an area, the construction of a treatment plant once again comes into the picture with its associated costs. For the land developer, economics place high on the cost-benefit scale. Environmental concerns must also place high. Minimal damage to the environment means a better quality of life and less future impact on economics and health.

## B. Wastewater Recycle/Reuse Systems

Wastewater recycle and reuse systems collect and process for subsequent use either all of the wastewater or a portion of it produced by particular activities. The intended reuse of the water determines the performance requirements of a wastewater recycle system, and is regulated accordingly by the DER under F.A.C. Rule 17-610. Most systems only process wastewater from bath facilities, bathroom sinks, and laundries for reuse in flushing water carriage toilets and outdoor irrigation. There are also on-site systems that process all wastewater from an individual establishment for reuse as potable water.

In many water short areas, wastewater reuse represents a feasible, cost-effective approach for effluent disposal and also reduces total demand for potable water. However, wastewater reuse in the Florida Keys is limited at this time to irrigation of two golf courses at Marathon and Key Colony Beach, which are inadequate in area to accept more than a portion of local flows.

Since many areas of the Florida Keys are periodically inundated with saltwater and have little soil mantle, agricultural development in the Florida Keys is minimal, including only five nurseries. This also probably reflects high land costs that would tend to make most agricultural operations noncompetitive. For the same reasons, there are few areas of grassland requiring irrigation, such as median strips, parks, and playing fields. The cost of piping filtered secondary effluent to the few potential sites would be very high.

With appropriate treatment, effluent may be suitable for water supply uses at some time in the future, in which case underground storage and recovery as described in the Monroe County 201 Facilities Plan may prove to be desirable for aesthetic and treatment purposes. At the present time, wastewater reuse is not a feasible method for effluent disposal in widespread applications; however, its potential resource value should not be precluded from future consideration.

#### 10.3.4 Development of the Sanitary Wastewater/Stormwater Master Plan

As previously discussed, it is expected that a Sanitary Wastewater/Stormwater Management Master Plan (SW/SMMP) will be undertaken and completed by 1995. One of the components necessary to be included in this study is an identification and assessment of areas which are not suitable for septic tank use because of unsuitable soils, inappropriate densities and age and type of existing septic systems. The septic tank and cesspool inventory followed by the proposed HRS inspection program is expected to partially provide the required data and assessments necessary as input to the SW/SMMP.

## 10.4 Proposed Level of Service (LOS) Standards

The levels of service standards for OSDS and package treatment plants will, as a result of the SW/SMMP, be modified or replaced by permanent standards that reflect the necessary levels of treatment and disposal throughout Monroe County.

#### 10.4.1 Package Treatment Plants

Package treatment plants performance is monitored through the submission of monthly operating reports and an annual summary to DER. The interim level of service standards for quantity and quality will be determined based on the individual package treatment plants design capacity and the ability of the plant to meet the effluent quality and operational standards set forth in Chapter 17-600, F.A.C.

The SW/SMMP will attempt to determine the effects of treatment plant effluent on water quality and shall recommend a LOS to supercede the existing LOS to minimize those effects determined to be detrimental to the designated OFW.

## 10.4.2 On Site Disposal Systems (OSDS)

The interim level of service pending completion of the OSDS evaluation and feasibility assessment for the SW/SMMP for on-site disposal systems will be in compliance with the requirements of the most recent versions of Chapter 10D-6 and Chapter 10D-6, Part II, F.A.C.

The interim level of service standards for OSDS will be superseded and replaced by permanent standards established as a result of completion of the SW/SMMP based on environment carrying capacity which addresses nutrient loading and maintains the quality of nearshore waters.

## 10.4.3 Present and Projected Future Ability to Meet Level of Service Standards

The level of service (LOS) standards presented are intended to provide an interim LOS in the remedial plan for wastewater treatment and disposal pending the completion of adequate research and testing to determine whether or not alternative methods are appropriate for use in the Florida Keys.

As previously indicated, a combined SW/SMMP is projected for completion by September 1995. One of the objectives of the plan is to determine the necessary level of treatment required in all developed and undeveloped areas of Monroe County. The plan will specify a rate structure for service as well as a funding mechanism for implementation. The plan will at a minimum take into consideration soil suitability, water table, degradation to nearshore water quality, and land use. Prior to implementing the SW/SMMP, the legal implications of an interim ordinance imposing at least the established density requirements of 10D-6 should be explored. OSDS treatment alternatives need to be considered for lots not meeting the established density criteria. The plan will include researching the feasibility of nutrient removal for OSDS and package treatment plants and include testing of prototypical OSDS systems in order to ascertain their performance and applicability for use under actual conditions.

## 10.4.4 Key Carrying Capacity Limitation, Facilities Inadequacies and Policy Constraints

The results of the SW/SMMP will indicate the location for and the type(s) and level of wastewater treatment systems to be utilized. Although Comprehensive Plan policies specifying methods of sanitary wastewater treatment systems and applicable locations and densities may affect the cost and distribution of development, sanitary sewer systems are not expected to be considered a carrying capacity limitation.

## 10.5 Sanitary Wastewater/Stormwater Management Master Plan

Numerous purpose and site specific studies have been conducted regarding the use and effect of various sewage treatment and disposal systems in Monroe County. Many of these research efforts have been directed at identifying specific impact areas or biotic communities in the nearshore waters of Monroe County while not being designed specifically to identify the causative discharge points which, in most cases, were beyond the scope of these studies. Although these studies will be reviewed and when applicable be incorporated in the Sanitary Wastewater/Stormwater Management Master Plan (SW/SMMP) design methodology, it is now recognized that a comprehensive effort beyond the magnitude of anything yet undertaken will be required. Implementation of the SW/SMMP will affect the fiscal, public and private operational characteristics presently in place related to drainage and sewage treatment systems utilized in Monroe County. Successful development and implementation of the SW/SMMP will require expertise of both the engineering and scientific disciplines as well as the commitment to finance the study at a level that allows definitive conclusions and recommendations to be developed. The success of the study also requires that the fiscal and political commitments at varying levels, both government and regulatory, remain in place throughout the duration of the development and implementation phases.

The goal of the SW/SMMP is to identify point and non-point sources of pollution and the associated water quality degradation in the Florida Keys. Because of the interrelated nature of wastewater effluent discharge and stormwater runoff effects on water quality and in order to maximize the cost effectiveness of the Plan, the SW/SMMP will address both wastewater treatment and stormwater management. The Plan will ultimately define the type of wastewater treatment and disposal methods and stormwater management techniques to be utilized by geographic service area. Allowable densities as permitted through Land Development Regulations will be a consideration in defining the types of treatment systems and may preclude the use of certain systems in area characterized by high density development. The conclusions of the SW/SMMP will be integrated through the amendment process into the Comprehensive Plan. The Monroe County efforts will be integrated with the activities of National Oceanic and Atmospheric Administration's (NOAA) Marine Sanctuaries Program (MSP) which was initiated in October 1990. This goal will be accomplished over the next four years in three phases as outlined below.

## 10.5.1 Phase One: Design, Analysis and Approval of Water Quality Monitoring Network (March 1992 - September 1992)

In order for Monroe County to benefit financially by coordinating its efforts with those of the MSP and to meet the requirements of the Stipulated Agreement between the County and DCA, it is imperative that Phase One be initiated by March of 1992. The MSP is undertaking the collection and synthesis of a voluminous data base pertaining to water quality degradation and its effects on the biota. Many of the components of the MSP, especially the data gathering and analysis efforts, will parallel the data requirements of the SW/SMMP. By integrating the County's master planning efforts and time frame for completion with the MSP schedule, the efforts of both agencies can be complemented in terms of available expertise. In addition, the integrated effort will allow for the coordination of conclusions and implementation activities.

## A. Defining the Research Parameters and Data Collection Methodology

Based on initial coordination meetings conducted between the Monroe County Comprehensive Plan and Marine Sanctuaries planning teams, it is evident that much of the data required to complete the SW/SMMP has been and continues to be generated by previously conducted research efforts and the present MSP activities. Much of the previously conducted research efforts were site specific with the goals not specifically applicable to the data analysis and comprehensive conclusion requirements of the SW/SMMP. Further the MSP water quality research efforts are an integral component of the overall SW/SMMP process but must be complemented with data collection and analysis specific to wastewater and stormwater issues and related effects. The Monroe County/MSP coordination effort must continue on a routine basis to assure that the best data is available in a manner that complements the efforts of both entities. If Monroe County is not able to initiate development of the SW/SMMP in a manner that parallels the MSP water quality data collection and analysis efforts in terms of the research and time frames, the ability to take full advantage of this data may be endangered.

#### B. Data Organization

The SW/SMMP efforts will, because of its complexity in terms of the amount and diversity of the data collected, be best served through utilization of a Geographical Information System (GIS). Establishment of the database on the GIS will facilitate subsequent data analysis, utilization and interpretation throughout and beyond the planning process. The database is expected to consist of at a minimum the location and specifications of existing sanitary wastewater treatment facilities, location, type and quantity of discharge, associated discharge quality parameters such as bacteriological quality, nutrient loading, BOD, COD, metals, TSS, and toxic or hazardous components. Biotic samples will be collected from various target populations or communities and will be analyzed for species composition and diversity, standing crop, biomass and individual organism condition. The initial data collection and utilization of GIS will establish the database from which ongoing planning and management decisions can be made. Modifications to the database can be easily incorporated as needed based on interactive data analysis.

#### C. Remote Sensing

Various remote sensing techniques will be employed to identify specific features and surface water quality conditions such as algal blooms, thermal plumes, turbid water plumes, denuded substrata in shallow waters, and previously identified discharges. The technique is particularly useful in identifying specific impact loci with onshore discharges thereby relating cause and effect mechanisms. Florescent tracer dyes will be utilized as appropriate to enhance the location of various plumes and generally improve on the usefulness of the data generated by this technique. This feature will enhance the design team's ability to select the most appropriate data and station locations for impact analysis and minimization.

## D. Selection and Approval of Data Parameters and Monitoring Stations

Based upon the results of the previously discussed research effort, a specific data collection protocol will be designed which will meet the data requirements and the SWSMMP's objective of improving nearshore water quality. By incorporating the data generated during the source analysis with previously known and project identified impact areas, the number and location of monitoring stations can be kept to a minimum while still providing the necessary information so that informed decisions can be made. To ensure the scientific validity of the study design, a comprehensive review of the monitoring protocol will be undertaken by the appropriate governmental entities and the scientific community during these initial states of the planning effort. This effort will attempt to eliminate the possibility of design team subjectivity affecting important environmental monitoring protocol design decisions. In conjunction with the HRS experimental and prototypic alternatives, OSDS will be selected for evaluation in Phase Two of this study.

## E. Funding Sources

The Florida Keys has been designated a National Marine Sanctuary, Outstanding Florida Waters, and an Area of Critical State Concern. In addition, the Nature Conservancy has designated the Keys one of the ten most significant ecological communities in the world. Significant initial work efforts will be directed to identifying additional and alternative funding sources on the Federal, State and private levels.

The Florida Keys National Marine Sanctuary Program has in the Phase II, Task 5 - Funding Sources Report (September, 1992 Draft) identified potential sources of funding for implementation of any necessary institutional and corrective actions related to water quality. The information used in this report has been gathered from review of Florida State regulations related to funding and analysis of funding options used in similar activities. This report should serve as an inventory of potential options that can be used to addressed certain aspects of the water quality issues in the FKNMS. (Batelle. September, 1992 Draft).

A wide range of options have been identified for addressing water quality issues in the Keys. The agencies and institutions that will be involved in implementing these options are diverse in terms of capabilities and resources. Many of the funding mechanisms discussed in this report could be used to address a number of different management and engineering options, and it will be the task of the agencies and institutions involved to determine which options are available to them. At this stage in the development of management plans for the FKNMS, no single preferred option, or set of options, has been recommended for addressing water quality issues in the Keys. Because of this, it is

difficult to determine the type and level of funding will have on the local economy. For this reason, this report does not recommend a specific suite of funding options to use nor does it contain an extensive analysis of economic impacts or potential revenue generation. (Batelle, September, 1992 Draft).

Following is a list of the potential funding sources identified in the Draft Task 5-Funding Sources Report:

#### Municipal Bonds

- General Obligation Bonds
- Revenue Bonds
- Certificates of Participation
- Pooled Bonds
- Private Activity Bonds

#### Tax Finance

- Florida State Level Tax Revenue
- Florida Local Level Tax Revenue
- Taxation Related to Water Quality Improvement

Cigarette and Other Tobacco Products Tax

Utilities Tax

Motor Fuels and Petroleum Production Taxes

Tourist Development and Impact Taxes

Foodfish and Shellfish Taxes

Litter Control Tax

Aquatic Lands Leasehold Tax

Pollutants Tax

Impact Taxes

**Property Taxes** 

Sales Tax Surtaxes

#### Grants and Loans

- Federal

U.S. Environmental Protection Agency (EPA)

U.S. Department of Agriculture

Department of Housing and Urban Development

National Park Service

U.S. Department of Commerce

- State

#### Rates

- Utility Rates

Capacity Futures

- On-Site Sewage Disposal Systems

#### Fees

- User Fees

Moorage Fees and Privilege Fees Discharge and Run-Off Fees

Inspection Fees

- Tolls
- Impact Fees

Development Fees

Use Impact Fees

- Fines and Penalties
- Licenses and Permits

Fishing and Hunting Boat Licenses and Registration

- Permits Special Assessments Donations/Charitable Trusts Privatization

- Operations Contracting
- Construction and Operations Contracting

## 10.5.2 Phase Two: Data Collection, Monitoring Analysis

(October 1992 - September 1994)

The magnitude of the water quality program has been generally identified but it is dependent upon the findings of the Phase One analysis. Phase Two, Data Collection, Monitoring and Analysis, consists of undertaking the vast majority of data gathering primarily associated with the environmental quality monitoring programs.

#### A. Establishment of Monitoring Stations

The monitoring station locations will be established in the field and permanently identified by one of several techniques. Discrete artificial canal, nearshore, offshore or deep water reference stations will be recorded by physical means in the field as well as electronic means within the GIS system. The producibility and subsequent trend analysis of the collected data are directly dependent upon the successful location of all sampling stations. It is therefore imperative that all stations be easily accessible and replaceable under varying climatic conditions. Aquatic, estuarine and marine monitoring will be conducted by a combination of sample collection and off site analyses as well as in situ analyses.

## B. Water Quality Sampling

Water quality samples will be collected and analyzed for the previously identified parameters from all stations at least quarterly and in direct relationship to specified conditions which directly impact nearshore water quality. Such conditions include, but are not necessarily limited, to catastrophic spills, abnormal tidal conditions, local and near field storm events, and special events.

## C. Biotic Community Sampling

Various biological samples will be collected both from the water column as well asbenthic substrate. These collections will include both faunal and floral associations to produce a broad based data set. These samples will be collected from the previously identified water quality sampling stations or appropriate relatable near field locations. The purpose of these collections will be to identify the health of the individual organisms as well as the health of the community associated with the specific water quality at that station.

#### D. Soil Samples

During the collection of benthic substrata samples, offshore substrata collections will be made to identify associated geophysical conditions. Onshore soil borings will be performed to identify specific soil conditions and to determine their hydrogeological properties relative to transmissivity, bacteriological attenuation, nutrient uptake, and adsorptive and absorptive capacities. These stations will be located as a result of facilities location reviews. Based on a review of soils diversity throughout the Keys, sufficient samples will be taken to identify soil specific features and eliminate monitoring protocol induced variability.

Evaluations of the performance of existing tanks at various population locations and under varying soil conditions will be undertaken. The level of density the system is expected to serve will be a consideration in the septic tank sampling and evaluation. These evaluations will consist of a treatment effectiveness, effluent hydrology and the relationship to the soil sample analysis described in Section 10.5.2D above.

#### F. Wastewater Treatment and Disposal Methods Evaluation

The following treatment and disposal systems will be evaluated based on the future land use scenario, associated allowable densities, and adaptability to environmental constraints. Treatment methods that will be evaluated include, but are not limited to, standard septic tanks, aerobic units, alternative OSDS, package treatment plants (secondary treatment, AWT, nutrient removal), and regional wastewater treatment plants. Effluent disposal options to be evaluated will include recharge, shallow and deep well injection, ocean discharge, irrigation reuse and wetland discharge.

#### G. Evaluation of Alternative OSDS

Alternative OSDS will be identified and tested under actual operating conditions. These test systems will be installed under the HRS guidelines contained in Chapter 10D-6.049 FAC. These guidelines specify that the use of an experimental system may require the establishment of procedures for routine maintenance, operational surveillance and environmental monitoring to ensure that the system is functioning properly. Alternative OSDS will be evaluated based on treatment effectiveness, specifically nutrient removal and economic feasibility. To confirm the effectiveness of any alternative OSDS the monitoring of discharges will be conducted for identical parameters and at the frequency utilized in the previously discussed water quality monitoring efforts. The discharges will be sampled for water quality parameters including bacteriological quality, nutrient concentrations, BOD, COD, metals, and TSS. It is expected that this monitoring and evaluation program will take a minimum of two years and should be initiated at the onset of Phase Two of the SW/SMMP.

#### H. Remote Sensing

Some or all of the following techniques will be utilized, as appropriate, in order to ascertain areas of discharge into surface waters that will require on site field analysis: color infrared aerial photography, multi spectral high altitude or satellite imagery, vertical black and white photography, and other techniques which may be identified during the Phase One project design. Following the identification of important discharge points, florescent tracer dyes will be utilized to confirm target areas of the nearshore waters which will be analyzed. The identification process may include both remote sensing techniques as well as water borne sampling to identify the aerial extent and time of passage of individual discharge plumes. This effort will be valuable in identifying specific parameters which will be analyzed for in the sediment and water column. The associated sessile biotic assemblage entrained within continuous plume areas will yield further valuable data on the realized affects of the measured discharge constituents. By interrelating data generated on the biota and discharge parameters, informed decisions can be made regarding the source discharge.

#### I. Phase Two Conclusions

Utilizing the data collected during Phase Two and the subsequent analysis and conclusions, the policies and parameters which will serve as the basis for development of the SW/SMMP will be stipulated. These conclusions are expected to confirm or rescind hypotheses associated with type and performance of OSDS applicable to the specific conditions, the use of boreholes, stormwater runoff attenuation, water quality trends identified in ongoing monitoring, recommendations associated with effluent, treatment levels of each type of system, and the systems' ongoing appropriateness in the Keys environment. The conclusions will be based upon information generated by the SW/SMMP, as well as other ongoing or recently completed ecological analyses of the nearshore region of the Florida Keys. As previously stated this effort will incorporate the cause and effect relationships between discharges, water quality degradation and biotic impacts or responses.

# 10.5.3 Phase Three: Development of the Sanitary Wastewater/Stormwater Management Master Plan (October 1994 - September 1995)

#### A. Presentation of Findings and Conclusions

A working paper containing the results of the Phase Two Conclusions will be developed to present findings of the study to the entities having jurisdiction and interest in minimization of water quality degradation. Based on these findings, the paper will contain the recommended policies and parameters for final development of the SW/SMMP. Results of the governmental agency/public review and any additional relevant input will be utilized to solidify these policies and parameters.

## B. Final Development of the Sanitary Wastewater/Stormwater Management Master Plan

The Sanitary Wastewater Element of the SW/SMMP will contain the following components:

- O The ultimate type of treatment and effluent disposal system to be utilized by geographic service area will be identified and graphically depicted.
- o Mandatory level of treatments for new and replacement systems including the criteria for attaining the adopted level.
- Schematic depiction and estimated construction costs associated with any necessary major support infrastructure for sanitary sewer facilities.
- o Potential funding sources available to implement requires capital improvements associated with the recommendations contained in the Master Plan.
- o Proposed rate structure for publicly owned and operated sewer system.
- o Recommendations for retrofitting specific existing facility deficiencies found to be causing significant water quality degradation and development of associated costs.
- Recommended ongoing monitoring program, beyond the adoption of the Sanitary Wastewater Component of the SW/SMMP, designed to assess the effectiveness of improvements and amended adopted levels of service on environmental conditions.

The Stormwater Management element of the SW/SMMP will contain the following components:

- Recommendations for retrofitting specific existing facility deficiencies found to not be meeting the adopted levels of service standards.
- o Evaluation of the establishment of a Stormwater Utility as an equitable means of implementing the identified stormwater management improvements.
- o Recommended ongoing monitoring program beyond the adoption of the Stormwater Management component of the SW/SMMP to assess the effect of implementing stormwater management improvements and amended levels of service on environmental conditions.

## **Bibliography**

Dade County, Dade County Potable Water Supply Well Protection Ordinance (Dade County Ordinance Section 24-12.1)

Florida Department of Environmental Regulation Florida Keys Monitoring Study (205-J) July 1989.

Florida Department of Environmental Regulations, DER Wastewater Management Manual, 1988.

Florida Department of Environmental Regulations Septic Tank Nonpoint Source Element, June 1979.

Florida Department of Environmental Regulation, Florida Nonpoint Source Assessment, Volumes I and II, August 1988.

Monroe County, (CH2M Hill), Monroe County 201 Facilities Plan, February 1979.

Monroe County Planning Department, Preliminary Policy Direction for the Comprehensive Plan, February 1991.

Florida Keys Aqueduct Authority, Policy and Procedure Handbook, December 1991.